Product Change Notification - SYST-27POMS876

Date:	28 Jul 2017
Product Category:	USB to Ethernet Controllers
Affected CPNs:	📄 📊
Notification subject:	Data Sheet - LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller Data Sheet Document Revision
Notification text:	

SYST-27POMS876

Microchip has released a new DeviceDoc for the LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller of devices. If you are using one of these devices please read the document located at LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller.

Notification Status: Final

Description of Change:
1) Figure 4-1, Power Connection Diagram, modified note under Figure 4-1

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 28 July 2017

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):	LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at http://www.microchip.com/PCN sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to microchipDIRECT and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

LAN7800-V/VSX

LAN7800T-V/VSX

LAN7800T-I/Y9X

LAN7800T-I/VSXVAO

LAN7800T-I/VSX

LAN7800T/Y9X

LAN7800T/VSX

LAN7800-I/Y9X

LAN7800-I/VSXVAO

LAN7800-I/VSX

LAN7800/Y9X

LAN7800/VSX