



# Product Change Notice

PCN Number: 15-0414-01  
Issue Date: 14-SEPTEMBER-2015

**Exar Corporation**  
[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

<b>PRODUCTS AFFECTED:</b>	SP7663ER-L	SP7663ER-L/TR	
	SP7662ER-L	SP7662ER-L/TR	

**CHANGE CATEGORY:**

<input type="checkbox"/> Material	<input type="checkbox"/> Process	<input type="checkbox"/> Package
<input checked="" type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input type="checkbox"/> Packing/Shipping
<input type="checkbox"/> Other:		

**DESCRIPTION OF CHANGE:**  
Metal layer change for yield improvement.

**IMPACT OF CHANGE:**  
There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 14-DECEMBER-2015

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**  
THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.