

Product Lifecycle Notice

Subject: Product Discontinuance / Obsolescence Notification Products

Publication Date: 6/10/2015

Revision Description:

Initial release

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,



Jeffrey Touvell

Intersil Corporation

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
24502BVA	6/10/2015	12/10/2015	6/10/2016	HM1-6514B
50838B	6/10/2015	12/10/2015	6/10/2016	None
5962-0620701Q3A	6/10/2015	12/10/2015	6/10/2016	None
5962-0620702Q3A	6/10/2015	12/10/2015	6/10/2016	None
5962-0620703Q2A	6/10/2015	12/10/2015	6/10/2016	None
5962-0620704Q2A	6/10/2015	12/10/2015	6/10/2016	None
5962-0620705Q3A	6/10/2015	12/10/2015	6/10/2016	None
5962-0620706Q3A	6/10/2015	12/10/2015	6/10/2016	None
5962-0620707Q2A	6/10/2015	12/10/2015	6/10/2016	None
5962-0620708Q2A	6/10/2015	12/10/2015	6/10/2016	None
5962-0623501QPC	6/10/2015	12/10/2015	6/10/2016	None
5962-0623502QPC	6/10/2015	12/10/2015	6/10/2016	None
5962-0623601QPC	6/10/2015	12/10/2015	6/10/2016	None
5962-0623602QPC	6/10/2015	12/10/2015	6/10/2016	None
5962-0625501QXC	6/10/2015	12/10/2015	6/10/2016	None
5962-8778301EA	6/10/2015	12/10/2015	6/10/2016	None
5962-8869002JA	6/10/2015	12/10/2015	6/10/2016	HM1-6642B
5962-8950201GC	6/10/2015	12/10/2015	6/10/2016	None
5962-8954801GC	6/10/2015	12/10/2015	6/10/2016	None
5962-8954801GCS2035	6/10/2015	12/10/2015	6/10/2016	None
5962-89620012A	6/10/2015	12/10/2015	6/10/2016	None
5962-9051801MEA	6/10/2015	12/10/2015	6/10/2016	None
5962-9054901MQA	6/10/2015	12/10/2015	6/10/2016	None
5962-9467701M2A	6/10/2015	12/10/2015	6/10/2016	None
5962M95A0501QXA	6/10/2015	12/10/2015	6/10/2016	None
5962M95A0501QYA	6/10/2015	12/10/2015	6/10/2016	None
7800302GC	6/10/2015	12/10/2015	6/10/2016	HA2-2640-2
7800302PA	6/10/2015	12/10/2015	6/10/2016	HA7-2640-2
81006122A	6/10/2015	12/10/2015	6/10/2016	None
81006222A	6/10/2015	12/10/2015	6/10/2016	HI4-5051
ACTS373DMSR-02	6/10/2015	12/10/2015	6/10/2016	None
ACTS373KMSR-02	6/10/2015	12/10/2015	6/10/2016	None
CD4071BDMSR	6/10/2015	12/10/2015	6/10/2016	None
CD4071BHSR	6/10/2015	12/10/2015	6/10/2016	None
CD4071BKMSR	6/10/2015	12/10/2015	6/10/2016	None
CD4073BDNSR	6/10/2015	12/10/2015	6/10/2016	None
CD4073BHNSR	6/10/2015	12/10/2015	6/10/2016	None
CD4073BKNSR	6/10/2015	12/10/2015	6/10/2016	None
CD4098BDNSR	6/10/2015	12/10/2015	6/10/2016	None
CD4098BHNSR	6/10/2015	12/10/2015	6/10/2016	None
CD4098BKNSR	6/10/2015	12/10/2015	6/10/2016	None
CD4503BKNSR	6/10/2015	12/10/2015	6/10/2016	None
CDP68HC68T1E	6/10/2015	12/10/2015	6/10/2016	CDP68HC68T1EZ
CDP68HC68T1M	6/10/2015	12/10/2015	6/10/2016	CDP68HC68T1MZ
CDP68HC68T1M2	6/10/2015	12/10/2015	6/10/2016	CDP68HC68T1M2Z
CDP68HC68T1M296	6/10/2015	12/10/2015	6/10/2016	CDP68HC68T1M2Z96
CDP68HC68T1M96	6/10/2015	12/10/2015	6/10/2016	CDP68HC68T1M296
CDP68HC68T1W	6/10/2015	12/10/2015	6/10/2016	None
CP80C86-2	6/10/2015	12/10/2015	6/10/2016	None
CP82C37A-5	6/10/2015	12/10/2015	6/10/2016	IS82C37A
CP82C50A-5	6/10/2015	12/10/2015	6/10/2016	CS82C50A-5Z
CP82C50A-5Z	6/10/2015	12/10/2015	6/10/2016	CS82C50A-5Z
CP82C52	6/10/2015	12/10/2015	6/10/2016	CP82C52Z
CP82C54-10	6/10/2015	12/10/2015	6/10/2016	CP82C54-10Z
CP82C54-12	6/10/2015	12/10/2015	6/10/2016	CP82C54-12Z
CP82C55A-5	6/10/2015	12/10/2015	6/10/2016	CP82C55A-5Z

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
CP82C59A-12	6/10/2015	12/10/2015	6/10/2016	CP82C59A-12Z
CP82C88	6/10/2015	12/10/2015	6/10/2016	None
CP82C88Z	6/10/2015	12/10/2015	6/10/2016	None
CP82C89	6/10/2015	12/10/2015	6/10/2016	None
CP82C89Z	6/10/2015	12/10/2015	6/10/2016	None
CS82C37A	6/10/2015	12/10/2015	6/10/2016	IS82C37A
CS82C37A-1296	6/10/2015	12/10/2015	6/10/2016	IS82C37A
CS82C37AZ	6/10/2015	12/10/2015	6/10/2016	IS82C37A
CS82C54-1096	6/10/2015	12/10/2015	6/10/2016	CS82C54-10, CS82C54-10Z96
CS82C54-12	6/10/2015	12/10/2015	6/10/2016	CS82C54-12Z
CS82C5496	6/10/2015	12/10/2015	6/10/2016	CS82C54, CS82C54Z96
CS82C54R2499	6/10/2015	12/10/2015	6/10/2016	CS82C54, CS82C54Z
CS82C55A-5	6/10/2015	12/10/2015	6/10/2016	CS82C55A-5Z
CS82C55A-596	6/10/2015	12/10/2015	6/10/2016	CS82C55A-5Z96
CS82C55A96	6/10/2015	12/10/2015	6/10/2016	CS82C55A, CS82C55AZ96
CS82C55AR2499	6/10/2015	12/10/2015	6/10/2016	CS82C55A, CS82C55AZ
CS82C59A	6/10/2015	12/10/2015	6/10/2016	CS82C59AZ
CS82C59A-12	6/10/2015	12/10/2015	6/10/2016	CS82C59A-12Z
CS82C59A96	6/10/2015	12/10/2015	6/10/2016	CS82C59AZ96
CS82C84A	6/10/2015	12/10/2015	6/10/2016	CP82C84A, CP82C84AZ
CS82C84AZ	6/10/2015	12/10/2015	6/10/2016	CP82C84A, CP82C84AZ
CS82C84AZ96	6/10/2015	12/10/2015	6/10/2016	CP82C84A, CP82C84AZ
D2-81434-LR	6/10/2015	12/10/2015	6/10/2016	D2-81433-LR
DG403DYZ-TS2457	6/10/2015	6/10/2016	#####	DG403DYZ-T
DG407DYZ-TS2705	6/10/2015	3/10/2016	3/10/2017	DG407DYZ-T
DG408DVZ-TS2568	6/10/2015	12/10/2015	6/10/2016	DG408DVZ-T
EL1516AIYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL1516AIYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL1516ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL1516ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL1516IYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL1516IYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL2045CSZ	6/10/2015	12/10/2015	6/10/2016	None
EL2045CSZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL2045CSZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL2227CSZ	6/10/2015	12/10/2015	6/10/2016	None
EL2227CSZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL2227CSZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL2227CYZ	6/10/2015	12/10/2015	6/10/2016	None
EL2227CYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL2227CYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL2250CSZ	6/10/2015	12/10/2015	6/10/2016	None
EL2250CSZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL2250CSZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL2276CSZ	6/10/2015	12/10/2015	6/10/2016	None
EL2276CSZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL2276CSZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL4544IGZS2729	6/10/2015	12/10/2015	6/10/2016	EL4544IGZ
EL5001IREZ	6/10/2015	12/10/2015	6/10/2016	None
EL5001IREZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5001IREZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5106ISZ	6/10/2015	12/10/2015	6/10/2016	None
EL5106ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5106ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5108ISZ	6/10/2015	12/10/2015	6/10/2016	None
EL5108ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5108ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL5108IWZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5111IYEZ	6/10/2015	12/10/2015	6/10/2016	None
EL5111IYEZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5111IYEZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5120TIWZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5123CZ	6/10/2015	12/10/2015	6/10/2016	None
EL5123CZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5123CZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5127CZ	6/10/2015	12/10/2015	6/10/2016	None
EL5127CZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5127CZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5162IWZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5163IWZ-T7
EL5162IWZ-T7A	6/10/2015	12/10/2015	6/10/2016	EL5163IWZ-T7A
EL5163ICZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5163IWZ-T7
EL5163ICZ-T7A	6/10/2015	12/10/2015	6/10/2016	EL5163IWZ-T7A
EL5173IYZ	6/10/2015	12/10/2015	6/10/2016	EL5173ISZ
EL5173IYZ-T13	6/10/2015	12/10/2015	6/10/2016	EL5173ISZ-T13
EL5173IYZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5173ISZ-T7
EL5176IYZ	6/10/2015	12/10/2015	6/10/2016	EL5171ISZ
EL5176IYZ-T13	6/10/2015	12/10/2015	6/10/2016	EL5171ISZ-T13
EL5176IYZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5171ISZ-T7
EL5178ISZ	6/10/2015	12/10/2015	6/10/2016	EL5174ISZ
EL5178ISZ-T13	6/10/2015	12/10/2015	6/10/2016	EL5174ISZ-T13
EL5178ISZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5174ISZ-T7
EL5178IYZ	6/10/2015	12/10/2015	6/10/2016	EL5174ISZ
EL5178IYZ-T13	6/10/2015	12/10/2015	6/10/2016	EL5174ISZ-T13
EL5178IYZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5174ISZ-T7
EL5205IYZ	6/10/2015	12/10/2015	6/10/2016	None
EL5205IYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5205IYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5211IYEZ	6/10/2015	12/10/2015	6/10/2016	None
EL5211IYEZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5211IYEZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5211TILZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5211TIYEZ	6/10/2015	12/10/2015	6/10/2016	None
EL5211TIYEZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5211TIYEZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5225IRZ	6/10/2015	12/10/2015	6/10/2016	None
EL5225IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5225IRZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5227CLZ	6/10/2015	12/10/2015	6/10/2016	None
EL5227CLZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5227CLZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5227CRZ	6/10/2015	12/10/2015	6/10/2016	None
EL5227CRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5227CRZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5236ISZ	6/10/2015	12/10/2015	6/10/2016	None
EL5236ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5236ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5236IYZ	6/10/2015	12/10/2015	6/10/2016	None
EL5236IYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5236IYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5237IYZ	6/10/2015	12/10/2015	6/10/2016	None
EL5237IYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5237IYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5260IYZ	6/10/2015	12/10/2015	6/10/2016	None
EL5260IYZ-T13	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL5260IYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5261ISZ	6/10/2015	12/10/2015	6/10/2016	None
EL5261ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5261ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5304IUZ	6/10/2015	12/10/2015	6/10/2016	None
EL5304IUZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5304IUZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5306ISZ	6/10/2015	12/10/2015	6/10/2016	EL5306IUZ
EL5306ISZ-T13	6/10/2015	12/10/2015	6/10/2016	EL5306IUZ-T13
EL5306ISZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5306IUZ-T7
EL5306IUZ-T7S2490	6/10/2015	12/10/2015	6/10/2016	EL5306IUZ-T7
EL5325AIREZ	6/10/2015	12/10/2015	6/10/2016	None
EL5325AIREZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5325AIREZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5327CLZ	6/10/2015	12/10/2015	6/10/2016	None
EL5327CLZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5327CLZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5327CRZ	6/10/2015	12/10/2015	6/10/2016	None
EL5327CRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5327CRZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5360ISZ	6/10/2015	12/10/2015	6/10/2016	None
EL5360ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5360ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5360IUZ	6/10/2015	12/10/2015	6/10/2016	None
EL5360IUZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5360IUZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5370IUZ	6/10/2015	12/10/2015	6/10/2016	None
EL5370IUZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5370IUZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5371IUZ	6/10/2015	12/10/2015	6/10/2016	EL5373IUZ
EL5371IUZ-T13	6/10/2015	12/10/2015	6/10/2016	EL5373IUZ-T13
EL5371IUZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5373IUZ-T7
EL5372IUZ	6/10/2015	12/10/2015	6/10/2016	EL5375IUZ
EL5372IUZ-T13	6/10/2015	12/10/2015	6/10/2016	EL5375IUZ-T13
EL5372IUZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5375IUZ-T7
EL5374IUZ	6/10/2015	12/10/2015	6/10/2016	EL5373IUZ
EL5374IUZ-T13	6/10/2015	12/10/2015	6/10/2016	EL5373IUZ-T13
EL5374IUZ-T7	6/10/2015	12/10/2015	6/10/2016	EL5373IUZ-T7
EL5411IREZ	6/10/2015	12/10/2015	6/10/2016	None
EL5411IREZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5411IREZ-T13R5379	6/10/2015	12/10/2015	6/10/2016	None
EL5411IREZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5411IREZ-T7R5379	6/10/2015	12/10/2015	6/10/2016	None
EL5411IRZ	6/10/2015	12/10/2015	6/10/2016	None
EL5411IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5411IRZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5411TILZ	6/10/2015	12/10/2015	6/10/2016	None
EL5411TILZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5411TILZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5411TIREZ	6/10/2015	12/10/2015	6/10/2016	None
EL5411TIREZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5411TIREZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5420CLZ	6/10/2015	12/10/2015	6/10/2016	None
EL5420CLZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5420CLZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5420TILZ	6/10/2015	12/10/2015	6/10/2016	None
EL5420TILZ-T13	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL5420TILZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5420TISZ	6/10/2015	12/10/2015	6/10/2016	None
EL5420TISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5420TISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5421CYZ	6/10/2015	12/10/2015	6/10/2016	None
EL5421CYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL5421CYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL5625ILZ	6/10/2015	12/10/2015	6/10/2016	None
EL5625ILZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL7104W	6/10/2015	12/10/2015	6/10/2016	None
EL7154CNZ	6/10/2015	12/10/2015	6/10/2016	EL7154CSZ
EL7156CNZ	6/10/2015	12/10/2015	6/10/2016	EL7156CSZ
EL7158W	6/10/2015	12/10/2015	6/10/2016	None
EL7182CN	6/10/2015	12/10/2015	6/10/2016	None
EL7182CSZ	6/10/2015	12/10/2015	6/10/2016	None
EL7182CSZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL7182CSZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL7222CSZE9044	6/10/2015	12/10/2015	6/10/2016	EL7222CSZ
EL7222CSZE9044-T7	6/10/2015	12/10/2015	6/10/2016	EL7222CSZ
EL7222CW	6/10/2015	12/10/2015	6/10/2016	None
EL7232CN	6/10/2015	12/10/2015	6/10/2016	EL7232CNZ
EL7252CN	6/10/2015	12/10/2015	6/10/2016	EL7252CSZ
EL7457CD	6/10/2015	12/10/2015	6/10/2016	None
EL7515IY-T7	6/10/2015	12/10/2015	6/10/2016	None
EL7515IYZ	6/10/2015	12/10/2015	6/10/2016	None
EL7515IYZS2695	6/10/2015	12/10/2015	6/10/2016	None
EL7515IYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL7515IYZ-T13S2695	6/10/2015	12/10/2015	6/10/2016	None
EL7515IYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL7515IYZ-T7S2695	6/10/2015	12/10/2015	6/10/2016	None
EL7531IY	6/10/2015	12/10/2015	6/10/2016	None
EL7531IY-T13	6/10/2015	12/10/2015	6/10/2016	None
EL7531IYZ	6/10/2015	12/10/2015	6/10/2016	None
EL7531IYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL7531IYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL7532IY-T13	6/10/2015	12/10/2015	6/10/2016	EL7532IYZ-T13
EL7535IY-T13	6/10/2015	12/10/2015	6/10/2016	EL7535IYZ-T13
EL7535IY-T7	6/10/2015	12/10/2015	6/10/2016	EL7535IYZ-T7
EL7536IYZS2695	6/10/2015	12/10/2015	6/10/2016	None
EL7536IYZ-T13S2695	6/10/2015	12/10/2015	6/10/2016	None
EL7536IYZ-T7S2695	6/10/2015	12/10/2015	6/10/2016	None
EL7563CREZ	6/10/2015	12/10/2015	6/10/2016	EL7554IREZ
EL7563CREZ-T13	6/10/2015	12/10/2015	6/10/2016	EL7554IREZ-T13
EL7563CREZ-T13S2705	6/10/2015	3/10/2016	3/10/2017	EL7554IREZ-T13
EL7563CREZ-T7	6/10/2015	12/10/2015	6/10/2016	EL7554IREZ-T7
EL7564CREZ	6/10/2015	12/10/2015	6/10/2016	ISL8024IRTAJZ-T
EL7564CREZ-T13	6/10/2015	12/10/2015	6/10/2016	ISL8024IRTAJZ-T
EL7564CREZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL8024IRTAJZ-T
EL7581IREZ	6/10/2015	12/10/2015	6/10/2016	None
EL7581IREZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL7581IREZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL7630IWTZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL7630IWTZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
EL7640AILTZ	6/10/2015	12/10/2015	6/10/2016	None
EL7640AILTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL7640AILTZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL7641AILTZ	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
EL7641AILTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL7641AILTZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL7642AILTZ	6/10/2015	12/10/2015	6/10/2016	None
EL7642AILTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL7642AILTZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL8108ILZ	6/10/2015	12/10/2015	6/10/2016	None
EL8108ILZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL8108ILZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL8108ISZ	6/10/2015	12/10/2015	6/10/2016	None
EL8108ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL8108ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL8171FSZ	6/10/2015	12/10/2015	6/10/2016	EL8170FSZ-T7
EL8171FSZ-T7	6/10/2015	12/10/2015	6/10/2016	EL8170FSZ-T7
EL8173FSZ	6/10/2015	12/10/2015	6/10/2016	EL8170FSZ-T7
EL8173FSZ-T7	6/10/2015	12/10/2015	6/10/2016	EL8170FSZ-T7
EL8200IYZ	6/10/2015	12/10/2015	6/10/2016	EL8201ISZ
EL8200IYZ-T13	6/10/2015	12/10/2015	6/10/2016	EL8201ISZ-T13
EL8200IYZ-T7	6/10/2015	12/10/2015	6/10/2016	EL8201ISZ-T7
EL8202IYZ	6/10/2015	12/10/2015	6/10/2016	None
EL8202IYZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL8202IYZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL8203ISZ	6/10/2015	12/10/2015	6/10/2016	None
EL8203ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL8203ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL8401ISZ	6/10/2015	12/10/2015	6/10/2016	None
EL8401ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL8401ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL8401IUZ	6/10/2015	12/10/2015	6/10/2016	None
EL8401IUZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL8401IUZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL8403ISZ	6/10/2015	12/10/2015	6/10/2016	None
EL8403ISZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL8403ISZ-T7	6/10/2015	12/10/2015	6/10/2016	None
EL8403IUZ	6/10/2015	12/10/2015	6/10/2016	None
EL8403IUZ-T13	6/10/2015	12/10/2015	6/10/2016	None
EL8403IUZ-T7	6/10/2015	12/10/2015	6/10/2016	None
HA0-2539B5454-6	6/10/2015	12/10/2015	6/10/2016	None
HA0-2625B5454-6	6/10/2015	12/10/2015	6/10/2016	None
HA0-5162B5454-6	6/10/2015	12/10/2015	6/10/2016	None
HA1-2400/883	6/10/2015	12/10/2015	6/10/2016	None
HA1-2420-2	6/10/2015	12/10/2015	6/10/2016	None
HA1-5320-5	6/10/2015	12/10/2015	6/10/2016	HA1-5320-2
HA1-5330-5	6/10/2015	12/10/2015	6/10/2016	None
HA2-5033-2	6/10/2015	12/10/2015	6/10/2016	None
HA2-5127/883	6/10/2015	12/10/2015	6/10/2016	None
HA3-5020-5Z	6/10/2015	12/10/2015	6/10/2016	HA9P5020-5Z, HA9P5020-5ZX96
HA4344BCBZ	6/10/2015	12/10/2015	6/10/2016	None
HA4344BCBZ96	6/10/2015	12/10/2015	6/10/2016	None
HA4600CPZ	6/10/2015	12/10/2015	6/10/2016	HA4600CBZ, HA4600CHZ96
HA5023IPZ	6/10/2015	12/10/2015	6/10/2016	HA5023IBZ
HA5024IBZ	6/10/2015	12/10/2015	6/10/2016	HA5023IBZ
HA5024IBZ96	6/10/2015	12/10/2015	6/10/2016	HA5023IBZ96
HA5024IPZ	6/10/2015	12/10/2015	6/10/2016	HA5023IBZ
HA7-2510/883	6/10/2015	12/10/2015	6/10/2016	None
HA7-2510/883S2035	6/10/2015	12/10/2015	6/10/2016	None
HA7-5033R5389	6/10/2015	12/10/2015	6/10/2016	None
HA0-50782R3562	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HAA0-51043R4192	6/10/2015	12/10/2015	6/10/2016	None
HAA0-51044R4193	6/10/2015	12/10/2015	6/10/2016	None
HAA0-51045R4194	6/10/2015	12/10/2015	6/10/2016	None
HAA0-51150S2677	6/10/2015	12/10/2015	6/10/2016	None
HAA0-52038R4488	6/10/2015	12/10/2015	6/10/2016	None
HAA4-50690R5131	6/10/2015	12/10/2015	6/10/2016	None
HAA-50945R4507	6/10/2015	12/10/2015	6/10/2016	None
HAA-50946R4508	6/10/2015	12/10/2015	6/10/2016	None
HAA-50947R4033	6/10/2015	12/10/2015	6/10/2016	None
HAA-51540AS2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-51541S2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-51543S2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-52471R4911	6/10/2015	12/10/2015	6/10/2016	None
HAA-52643S2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-52666S2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-52741S2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-52742S2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-52760S2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-52900S2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-53103R5187	6/10/2015	12/10/2015	6/10/2016	None
HAA-53108S2571	6/10/2015	12/10/2015	6/10/2016	None
HAA-53411BS2571	6/10/2015	12/10/2015	6/10/2016	None
HAA9-51150R4551	6/10/2015	12/10/2015	6/10/2016	None
HAA9-51150R4551/RAD	6/10/2015	12/10/2015	6/10/2016	None
HAA9-51150S2677	6/10/2015	12/10/2015	6/10/2016	None
HAA9-51150S2677/DPA	6/10/2015	12/10/2015	6/10/2016	None
HAA9Q-53721ZR5141	6/10/2015	12/10/2015	6/10/2016	None
HAA9Q-53721ZR5141-T	6/10/2015	12/10/2015	6/10/2016	None
HC4P5504BZR4741-104	6/10/2015	12/10/2015	6/10/2016	None
HC5503CBZ	6/10/2015	12/10/2015	6/10/2016	HC5503PRCBZ
HC5503CBZ96	6/10/2015	12/10/2015	6/10/2016	HC5503PRCBZ96
HC5503PRIBZ	6/10/2015	12/10/2015	6/10/2016	HC5503PRCBZ
HC5503PRIBZ96	6/10/2015	12/10/2015	6/10/2016	HC5503PRCBZ96
HC5503TCBZ	6/10/2015	12/10/2015	6/10/2016	HC5503PRCBZ
HC5503TCBZ96	6/10/2015	12/10/2015	6/10/2016	HC5503PRCBZ96
HC55120CMZ	6/10/2015	12/10/2015	6/10/2016	None
HC55121IMZ	6/10/2015	12/10/2015	6/10/2016	None
HC55130IMZ	6/10/2015	12/10/2015	6/10/2016	None
HC55140IMZ	6/10/2015	12/10/2015	6/10/2016	None
HC55142IMZ	6/10/2015	12/10/2015	6/10/2016	None
HC55142IMZ96	6/10/2015	12/10/2015	6/10/2016	None
HC55150CMZ	6/10/2015	12/10/2015	6/10/2016	None
HC5515CMZ	6/10/2015	12/10/2015	6/10/2016	None
HD0-6402RB6092-6	6/10/2015	12/10/2015	6/10/2016	None
HD0-82C54B6092-6	6/10/2015	12/10/2015	6/10/2016	None
HD1-4702/883	6/10/2015	12/10/2015	6/10/2016	None
HD3-4702-9	6/10/2015	12/10/2015	6/10/2016	None
HD3-4702-9Z	6/10/2015	12/10/2015	6/10/2016	None
HD3-6402R-9	6/10/2015	12/10/2015	6/10/2016	None
HD3-6402R-9Z	6/10/2015	12/10/2015	6/10/2016	None
HD3-6408-9	6/10/2015	12/10/2015	6/10/2016	HD3-6408-9Z
HD9P6409-9	6/10/2015	12/10/2015	6/10/2016	None
HFA1110IBZ	6/10/2015	12/10/2015	6/10/2016	HFA1112IBZ
HFA1112IPZ	6/10/2015	12/10/2015	6/10/2016	HFA1112IBZ
HFA1113IBZ	6/10/2015	12/10/2015	6/10/2016	None
HFA1113IBZ96	6/10/2015	12/10/2015	6/10/2016	None
HFA1130W	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HFA1145IBZ	6/10/2015	12/10/2015	6/10/2016	None
HFA1145IPZ	6/10/2015	12/10/2015	6/10/2016	None
HFA1412IBZ	6/10/2015	12/10/2015	6/10/2016	None
HFA1412IPZ	6/10/2015	12/10/2015	6/10/2016	None
HFA3046BZ96	6/10/2015	12/10/2015	6/10/2016	HFA3046BZ
HFA3096W	6/10/2015	12/10/2015	6/10/2016	None
HFA3101W	6/10/2015	12/10/2015	6/10/2016	None
HFA3127W	6/10/2015	12/10/2015	6/10/2016	None
HFA3128BZ	6/10/2015	12/10/2015	6/10/2016	None
HFA3128BZ96	6/10/2015	12/10/2015	6/10/2016	None
HFA3128RZ	6/10/2015	12/10/2015	6/10/2016	None
HFA3128RZ96	6/10/2015	12/10/2015	6/10/2016	None
HFA3128W	6/10/2015	12/10/2015	6/10/2016	None
HFA3135W	6/10/2015	12/10/2015	6/10/2016	None
HI0-0303B5454-6	6/10/2015	12/10/2015	6/10/2016	None
HI0-1818AB5454-6	6/10/2015	12/10/2015	6/10/2016	None
HI1-0390-2	6/10/2015	12/10/2015	6/10/2016	None
HI1-0507-2	6/10/2015	12/10/2015	6/10/2016	None
HI1-1818A-2	6/10/2015	12/10/2015	6/10/2016	None
HI1-5047-2	6/10/2015	12/10/2015	6/10/2016	None
HI1-565AJD-5	6/10/2015	12/10/2015	6/10/2016	None
HI2-0200/883	6/10/2015	12/10/2015	6/10/2016	None
HI3-0200-5Z	6/10/2015	12/10/2015	6/10/2016	None
HI4P0201-5Z	6/10/2015	12/10/2015	6/10/2016	None
HI4P0549-5Z	6/10/2015	12/10/2015	6/10/2016	None
HI5628/6INZ	6/10/2015	12/10/2015	6/10/2016	None
HI5628INZ	6/10/2015	12/10/2015	6/10/2016	None
HI5714/4CBZ	6/10/2015	12/10/2015	6/10/2016	None
HI5714/7CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HI5714/W	6/10/2015	12/10/2015	6/10/2016	None
HI5728/6INZ	6/10/2015	12/10/2015	6/10/2016	None
HI5728INZ	6/10/2015	12/10/2015	6/10/2016	None
HI5728INZ-T	6/10/2015	12/10/2015	6/10/2016	None
HI5731BIPZ	6/10/2015	12/10/2015	6/10/2016	HI5731BIBZ
HI5731W	6/10/2015	12/10/2015	6/10/2016	None
HI5735KCBZ	6/10/2015	12/10/2015	6/10/2016	None
HI5741BIBZ	6/10/2015	12/10/2015	6/10/2016	None
HI5741BIBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HI5746KCAZ	6/10/2015	12/10/2015	6/10/2016	None
HI5746KCBZ	6/10/2015	12/10/2015	6/10/2016	None
HI5746KCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HI5762/6INZ	6/10/2015	12/10/2015	6/10/2016	None
HI5766KCAZ	6/10/2015	12/10/2015	6/10/2016	None
HI5766KCBZ	6/10/2015	12/10/2015	6/10/2016	None
HI5767/2CAZ	6/10/2015	12/10/2015	6/10/2016	None
HI5767/2CBZ	6/10/2015	12/10/2015	6/10/2016	None
HI5767/2IAZ	6/10/2015	12/10/2015	6/10/2016	None
HI5767/4CAZ	6/10/2015	12/10/2015	6/10/2016	None
HI5767/4CBZ	6/10/2015	12/10/2015	6/10/2016	None
HI5767/4CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HI5767/6CAZ	6/10/2015	12/10/2015	6/10/2016	None
HI5767/6CBZ	6/10/2015	12/10/2015	6/10/2016	None
HI5767/6CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HI5767/6IBZ	6/10/2015	12/10/2015	6/10/2016	None
HI5805BIBZ	6/10/2015	12/10/2015	6/10/2016	None
HI9P0509-5Z	6/10/2015	12/10/2015	6/10/2016	None
HIN207CAZ	6/10/2015	12/10/2015	6/10/2016	HIN207ECAZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HIN207CAZ-T	6/10/2015	12/10/2015	6/10/2016	HIN207ECAZ-T
HIN208CBZ	6/10/2015	12/10/2015	6/10/2016	HIN208ECBZ
HIN208CBZ-T	6/10/2015	12/10/2015	6/10/2016	HIN208ECBZ-T
HIN232EIVZ	6/10/2015	12/10/2015	6/10/2016	HIN232ECAZ
HIN232EIVZ-T	6/10/2015	12/10/2015	6/10/2016	HIN232ECAZ-T
HIN236CBZ	6/10/2015	12/10/2015	6/10/2016	ICL3243ECBZ
HIN237CBZ	6/10/2015	12/10/2015	6/10/2016	ICL3243ECBZ
HIN237CBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3243ECBZ
HIN238CPZ	6/10/2015	12/10/2015	6/10/2016	HIN238CBZ
HIN240CNZ	6/10/2015	12/10/2015	6/10/2016	None
HIN240CNZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIN241CAZ	6/10/2015	12/10/2015	6/10/2016	None
HIN241CBZ	6/10/2015	12/10/2015	6/10/2016	None
HIN241CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIN241IBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP1011ACBZA	6/10/2015	12/10/2015	6/10/2016	None
HIP1011ACBZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP1011BCBZA	6/10/2015	12/10/2015	6/10/2016	None
HIP1011BCBZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP1011CBZA	6/10/2015	12/10/2015	6/10/2016	None
HIP1011CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP1011CBZA-TS2490A	6/10/2015	12/10/2015	6/10/2016	None
HIP1011CBZA-TS2568	6/10/2015	12/10/2015	6/10/2016	None
HIP1011DCAZA	6/10/2015	12/10/2015	6/10/2016	None
HIP1011DCAZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP1011ECAZA	6/10/2015	12/10/2015	6/10/2016	None
HIP1011ECAZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP1012ACBZA	6/10/2015	12/10/2015	6/10/2016	None
HIP1012ACBZAS2695	6/10/2015	12/10/2015	6/10/2016	None
HIP1012ACBZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP1012ACBZA-TS2490A	6/10/2015	12/10/2015	6/10/2016	None
HIP1012ACBZA-TS2490S	6/10/2015	12/10/2015	6/10/2016	None
HIP1012ACBZA-TS2568	6/10/2015	12/10/2015	6/10/2016	None
HIP1012ACBZA-TS2695	6/10/2015	12/10/2015	6/10/2016	None
HIP1013CBZA	6/10/2015	12/10/2015	6/10/2016	None
HIP1013CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP2100IB	6/10/2015	12/10/2015	6/10/2016	HIP2100IBZ
HIP2100IBT	6/10/2015	12/10/2015	6/10/2016	HIP2100IBZT
HIP2100IBZTS2038	6/10/2015	12/10/2015	6/10/2016	HIP2100IBZT
HIP2100IR4Z	6/10/2015	12/10/2015	6/10/2016	HIP2100IRZ
HIP2100IR4ZT	6/10/2015	12/10/2015	6/10/2016	HIP2100IRZT
HIP2100IY	6/10/2015	12/10/2015	6/10/2016	None
HIP2101EIB	6/10/2015	12/10/2015	6/10/2016	HIP2101EIBZ
HIP2101IB	6/10/2015	12/10/2015	6/10/2016	HIP2101IBZ
HIP2101IW	6/10/2015	12/10/2015	6/10/2016	None
HIP2101IY	6/10/2015	12/10/2015	6/10/2016	None
HIP2120FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
HIP2120FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP2121FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
HIP2121FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP2122FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
HIP2122FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP2123FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
HIP2123FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP4020IB	6/10/2015	12/10/2015	6/10/2016	HIP4020IBZ
HIP4080AIW	6/10/2015	12/10/2015	6/10/2016	None
HIP4081AIBZR5525-2	6/10/2015	12/10/2015	6/10/2016	HIP4081AIBZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HIP4081AIBZR5525-3	6/10/2015	12/10/2015	6/10/2016	HIP4081AIBZ
HIP4081AIBZR5525-4	6/10/2015	12/10/2015	6/10/2016	HIP4081AIBZ
HIP4081AIBZTR5525-2	6/10/2015	12/10/2015	6/10/2016	HIP4081AIBZT
HIP4081AIBZTR5525-3	6/10/2015	12/10/2015	6/10/2016	HIP4081AIBZT
HIP4081AIBZTR5525-4	6/10/2015	12/10/2015	6/10/2016	HIP4081AIBZT
HIP4081AIP	6/10/2015	12/10/2015	6/10/2016	HIP4081AIPZ
HIP4081AIW	6/10/2015	12/10/2015	6/10/2016	None
HIP4081AIY	6/10/2015	12/10/2015	6/10/2016	None
HIP4082IP	6/10/2015	12/10/2015	6/10/2016	HIP4082IPZ
HIP4083ABT	6/10/2015	12/10/2015	6/10/2016	HIP4083ABZT
HIP4083APZ	6/10/2015	12/10/2015	6/10/2016	HIP4083ABZ
HIP4086ABZATS2490S	6/10/2015	12/10/2015	6/10/2016	HIP4086ABZT
HIP4086AW	6/10/2015	12/10/2015	6/10/2016	None
HIP4086AY	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCBZA	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCBZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCRZ-TS2462	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCVZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCVZA	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCVZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCVZA-TS2568	6/10/2015	12/10/2015	6/10/2016	None
HIP6004BCVZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6004CBZ-TS2462	6/10/2015	12/10/2015	6/10/2016	None
HIP6004DCBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6004DCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6004DCBZ-TS2462	6/10/2015	12/10/2015	6/10/2016	None
HIP6004DCRZ-TS2462	6/10/2015	12/10/2015	6/10/2016	None
HIP6004ECBZ-TS2568	6/10/2015	12/10/2015	6/10/2016	HIP6004ECBZ-T
HIP6004ECVZ	6/10/2015	12/10/2015	6/10/2016	HIP6004ECBZ
HIP6004ECVZ-T	6/10/2015	12/10/2015	6/10/2016	HIP6004ECBZ-T
HIP6004ECVZ-TS2568	6/10/2015	12/10/2015	6/10/2016	HIP6004ECBZ-T
HIP6006CBZ-TS2604	6/10/2015	3/10/2016	3/10/2017	HIP6006CBZ-T
HIP6012CBZR5226	6/10/2015	12/10/2015	6/10/2016	HIP6012CBZ
HIP6012CBZ-TR5226	6/10/2015	12/10/2015	6/10/2016	HIP6012CBZ-T
HIP6013CBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6013CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6018BCBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6018BCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6019BCBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6019BCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6021CBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6021CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6301CBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6301CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6301VCBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6301VCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6302VCBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6302VCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6311ACBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6311ACBZA	6/10/2015	12/10/2015	6/10/2016	None
HIP6311ACBZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6311ACBZA-TS2568	6/10/2015	12/10/2015	6/10/2016	None
HIP6311ACBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6311CBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6311CBZA	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HIP6311CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6311CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6501ACBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6501ACBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6503CBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6503CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6601BECBZ	6/10/2015	12/10/2015	6/10/2016	HIP6601BCBZ
HIP6601BECBZA	6/10/2015	12/10/2015	6/10/2016	HIP6601BCBZA
HIP6601BECBZA-T	6/10/2015	12/10/2015	6/10/2016	HIP6601BCBZA-T
HIP6601BECBZ-T	6/10/2015	12/10/2015	6/10/2016	HIP6601BCBZ-T
HIP6601BW	6/10/2015	12/10/2015	6/10/2016	None
HIP6602BCBZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6602BCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6602BCRZ	6/10/2015	12/10/2015	6/10/2016	None
HIP6602BCRZA	6/10/2015	12/10/2015	6/10/2016	None
HIP6602BCRZA-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6602BCRZ-T	6/10/2015	12/10/2015	6/10/2016	None
HIP6603BECBZ	6/10/2015	12/10/2015	6/10/2016	HIP6603BCBZ
HIP6603BECBZ-T	6/10/2015	12/10/2015	6/10/2016	HIP6603BCBZ-T
HIP6603BW	6/10/2015	12/10/2015	6/10/2016	None
HIP6604BCRZ-TS2705	6/10/2015	3/10/2016	3/10/2017	HIP6603BCBZ-T
HIP9011ABZTS2668	6/10/2015	6/10/2016	#####	HIP9011ABZT
HMP8117CN	6/10/2015	12/10/2015	6/10/2016	None
HMP8117CNZ	6/10/2015	12/10/2015	6/10/2016	None
HMP8156ACN	6/10/2015	12/10/2015	6/10/2016	None
HMP8156ACNZ	6/10/2015	12/10/2015	6/10/2016	None
HSO-1100RH/SAMPLE	6/10/2015	12/10/2015	6/10/2016	None
HSO-1100RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HSO-302EH-Q	6/10/2015	12/10/2015	6/10/2016	None
HSO-302RH/SAMPLE	6/10/2015	12/10/2015	6/10/2016	None
HSO-302RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HSO-307RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HSO-50416R4514	6/10/2015	12/10/2015	6/10/2016	None
HSO-50416R5152	6/10/2015	12/10/2015	6/10/2016	None
HSO-82C85RH/SAMPLE	6/10/2015	12/10/2015	6/10/2016	None
HSO-82C85RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HSO-CMP05RH-QS2677	6/10/2015	12/10/2015	6/10/2016	None
HSO-REF05RH-QS2677	6/10/2015	12/10/2015	6/10/2016	None
HS1-246RH/PROTO	6/10/2015	12/10/2015	6/10/2016	None
HS1-246RH-8	6/10/2015	12/10/2015	6/10/2016	None
HS1-246RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS1-248RH/PROTO	6/10/2015	12/10/2015	6/10/2016	None
HS1-248RH-8	6/10/2015	12/10/2015	6/10/2016	None
HS1-248RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS1-302EH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS1-302RH-8	6/10/2015	12/10/2015	6/10/2016	None
HS1-302RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS1-82C55ARH-8	6/10/2015	12/10/2015	6/10/2016	None
HS1-82C55ARH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS1-82C85RH-8	6/10/2015	12/10/2015	6/10/2016	None
HS1-82C85RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS4P-3282R4648	6/10/2015	12/10/2015	6/10/2016	None
HS7B-1100RH/PROTO	6/10/2015	12/10/2015	6/10/2016	None
HS7B-1100RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS9-246RH/PROTO	6/10/2015	12/10/2015	6/10/2016	None
HS9-246RH-8	6/10/2015	12/10/2015	6/10/2016	None
HS9-246RH-Q	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
HS9-248RH/PROTO	6/10/2015	12/10/2015	6/10/2016	None
HS9-248RH-8	6/10/2015	12/10/2015	6/10/2016	None
HS9-248RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS9-302EH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS9-302RH/PROTO	6/10/2015	12/10/2015	6/10/2016	None
HS9-302RH-8	6/10/2015	12/10/2015	6/10/2016	None
HS9-302RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS9-50416R2559	6/10/2015	12/10/2015	6/10/2016	None
HS9-50509R1991	6/10/2015	12/10/2015	6/10/2016	None
HS9-50510R1992	6/10/2015	12/10/2015	6/10/2016	None
HS9-82C85RH-8	6/10/2015	12/10/2015	6/10/2016	None
HS9-82C85RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS9-CMP05RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS9-CMP05RH-Q/RAD	6/10/2015	12/10/2015	6/10/2016	None
HS9-CMP05RH-QS2677	6/10/2015	12/10/2015	6/10/2016	None
HS9-CMP05RHS2677/DPA	6/10/2015	12/10/2015	6/10/2016	None
HS9-REF05RH-Q	6/10/2015	12/10/2015	6/10/2016	None
HS9-REF05RH-Q/RAD	6/10/2015	12/10/2015	6/10/2016	None
HS9-REF05RH-QS2677	6/10/2015	12/10/2015	6/10/2016	None
HS9-REF05RHS2677/DPA	6/10/2015	12/10/2015	6/10/2016	None
HSP43124SC-45	6/10/2015	12/10/2015	6/10/2016	None
HSP43124SC-45Z	6/10/2015	12/10/2015	6/10/2016	None
HSP43168JC-33	6/10/2015	12/10/2015	6/10/2016	None
HSP43168JC-33Z	6/10/2015	12/10/2015	6/10/2016	None
HSP43216JC-52	6/10/2015	12/10/2015	6/10/2016	None
HSP43216JC-52Z	6/10/2015	12/10/2015	6/10/2016	None
HSP43216VC-52	6/10/2015	12/10/2015	6/10/2016	None
HSP43216VC-52Z	6/10/2015	12/10/2015	6/10/2016	None
HSP43220JC-25	6/10/2015	12/10/2015	6/10/2016	None
HSP43220JC-25Z	6/10/2015	12/10/2015	6/10/2016	None
HSP43220JC-33	6/10/2015	12/10/2015	6/10/2016	None
HSP43220JC-33Z	6/10/2015	12/10/2015	6/10/2016	None
HSP45106JC-25	6/10/2015	12/10/2015	6/10/2016	None
HSP45106JC-25Z	6/10/2015	12/10/2015	6/10/2016	None
HSP45106JC-33	6/10/2015	12/10/2015	6/10/2016	None
HSP45106JC-33Z	6/10/2015	12/10/2015	6/10/2016	None
HSP45116AVC-52	6/10/2015	12/10/2015	6/10/2016	None
HSP45116AVC-52Z	6/10/2015	12/10/2015	6/10/2016	None
HSP50210JC-52	6/10/2015	12/10/2015	6/10/2016	None
HSP50210JC-52Z	6/10/2015	12/10/2015	6/10/2016	None
HSP50210JI-52	6/10/2015	12/10/2015	6/10/2016	None
HSP50210JI-52Z	6/10/2015	12/10/2015	6/10/2016	None
HSP9501JC-32	6/10/2015	12/10/2015	6/10/2016	None
HVS1535A3	6/10/2015	12/10/2015	6/10/2016	None
ICL3217CAZ	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217CAZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217CBZ	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217CBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217ECAZ	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217ECAZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217ECBZ	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217ECBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217EIAZ	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217EIAZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217EIBZ	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217EIBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217IAZ	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ICL3217IAZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217IBZ	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3217IBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3238ECAZ
ICL3223CPZ	6/10/2015	12/10/2015	6/10/2016	ICL3223ECVZ
ICL3225CPZ	6/10/2015	12/10/2015	6/10/2016	ICL3225ECAZ
ICL3225ECPZ	6/10/2015	12/10/2015	6/10/2016	ICL3225ECAZ
ICL3237CAZ	6/10/2015	12/10/2015	6/10/2016	ICL3237ECAZ
ICL3237CAZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3237ECAZ
ICL3237IAZ	6/10/2015	12/10/2015	6/10/2016	ICL3237EIAZ
ICL3237IAZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3237EIAZ
ICL3241CBZ	6/10/2015	12/10/2015	6/10/2016	ICL3241EIVZ
ICL3241CBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3241EIVZ
ICL3241ECBZ	6/10/2015	12/10/2015	6/10/2016	ICL3241EIVZ
ICL3241ECBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3241EIVZ
ICL3241EIBZ	6/10/2015	12/10/2015	6/10/2016	ICL3241EIVZ
ICL3241EIBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3241EIVZ
ICL3241IBZ	6/10/2015	12/10/2015	6/10/2016	ICL3241EIVZ
ICL3241IBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3241EIVZ
ICL3245ECBZ	6/10/2015	12/10/2015	6/10/2016	ICL3245EIAZ
ICL3245ECBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3245EIAZ
ICL3245ECVZ	6/10/2015	12/10/2015	6/10/2016	ICL3245EIAZ
ICL3245ECVZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3245EIAZ
ICL3245IVZ	6/10/2015	12/10/2015	6/10/2016	ICL3245EIAZ
ICL3245IVZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3245EIAZ
ICL7107C/W	6/10/2015	12/10/2015	6/10/2016	None
ICL7660W	6/10/2015	12/10/2015	6/10/2016	None
ICL7663SACBA	6/10/2015	12/10/2015	6/10/2016	ICL7663SACBAZA
ICL7663SACBA-T	6/10/2015	12/10/2015	6/10/2016	ICL7663SACBAZA-T
ICL7663SCBA	6/10/2015	12/10/2015	6/10/2016	ICL7663SCBAZA
ICL7663SCPA	6/10/2015	12/10/2015	6/10/2016	ICL7663SCPAZ
ICL7663SW	6/10/2015	12/10/2015	6/10/2016	None
ICL7665SACBA	6/10/2015	12/10/2015	6/10/2016	ICL7665SACBAZ
ICL7665SACBA-T	6/10/2015	12/10/2015	6/10/2016	ICL7665SACBAZ-T
ICL7665SACPA	6/10/2015	12/10/2015	6/10/2016	ICL7665SACPAZ
ICL7665SAIBA	6/10/2015	12/10/2015	6/10/2016	ICL7665SAIBAZA
ICL7665SAIPA	6/10/2015	12/10/2015	6/10/2016	ICL7665SAIPAZ
ICL7665SCBA	6/10/2015	12/10/2015	6/10/2016	ICL7665SCBAZ
ICL7665SCPA	6/10/2015	12/10/2015	6/10/2016	ICL7665SCPAZ
ICL7665SIBA-T	6/10/2015	12/10/2015	6/10/2016	ICL7665SIBAZ-T
ICL7667CBA	6/10/2015	12/10/2015	6/10/2016	ICL7667CBAZA
ICL7667CBA-T	6/10/2015	12/10/2015	6/10/2016	ICL7667CBAZA-T
ICL7673CBA	6/10/2015	12/10/2015	6/10/2016	ICL7673CBAZA-T
ICL7673CPA	6/10/2015	12/10/2015	6/10/2016	ICL7673CPAZ
ICM7211AMIPL	6/10/2015	12/10/2015	6/10/2016	ICM7211AMIPLZ
ICM7218B/W	6/10/2015	12/10/2015	6/10/2016	None
ICM7218DIJR5254	6/10/2015	12/10/2015	6/10/2016	ICM7218DIJI
ICM7228AIBI	6/10/2015	12/10/2015	6/10/2016	ICM7228AIBIZ
ICM7228AIPi	6/10/2015	12/10/2015	6/10/2016	ICM7228AIPIZ
ICM7228BIBI	6/10/2015	12/10/2015	6/10/2016	ICM7228BIBIZ
ICM7228BIPI	6/10/2015	12/10/2015	6/10/2016	ICM7228BIPIZ
ICM7228CIBI	6/10/2015	12/10/2015	6/10/2016	ICM7228CIBIZ
ICM7228CIPI	6/10/2015	12/10/2015	6/10/2016	ICM7228CIPIZ
ICM7242CBAZ	6/10/2015	12/10/2015	6/10/2016	None
ICM7242CBAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ICM7242IBAZ	6/10/2015	12/10/2015	6/10/2016	None
ICM7242IBAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ICM7243AIM44Z	6/10/2015	12/10/2015	6/10/2016	ICM7244AIM44Z

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ICM7243AIM44ZT	6/10/2015	12/10/2015	6/10/2016	ICM7244AIM44ZT
ICM7243AIPLZ	6/10/2015	12/10/2015	6/10/2016	None
ICM7243BIPL	6/10/2015	12/10/2015	6/10/2016	None
ID82C82	6/10/2015	12/10/2015	6/10/2016	None
ID82C86H	6/10/2015	12/10/2015	6/10/2016	None
IPM6220ACAZ	6/10/2015	12/10/2015	6/10/2016	None
IPM6220ACAZA-T	6/10/2015	12/10/2015	6/10/2016	None
IPM6220ACAZ-T	6/10/2015	12/10/2015	6/10/2016	None
IS80C286-20R5524	6/10/2015	12/10/2015	6/10/2016	IS80C286-20
IS82C37A-5	6/10/2015	12/10/2015	6/10/2016	IS82C37A
IS82C50A-5	6/10/2015	12/10/2015	6/10/2016	IS82C50A-5Z
IS82C55A96	6/10/2015	12/10/2015	6/10/2016	IS82C55A, IS82C55AZ96
IS82C59AX96	6/10/2015	12/10/2015	6/10/2016	IS82C59A, IS82C59AZX96
ISL12023IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12023IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12025IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12025IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12027AIB27Z	6/10/2015	12/10/2015	6/10/2016	None
ISL12027AIB27Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12027AIV27Z	6/10/2015	12/10/2015	6/10/2016	None
ISL12027AIV27Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12027IVAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12027IVAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12027IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12027IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12028AIB27Z	6/10/2015	12/10/2015	6/10/2016	None
ISL12028AIB27Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12028AIV27Z	6/10/2015	12/10/2015	6/10/2016	None
ISL12028AIV27Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IB27AZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IB27AZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IB30AZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IB30AZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IBAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IBAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IV27AZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IV27AZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IV30AZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IV30AZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IVAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12028IVAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029AIB27Z	6/10/2015	12/10/2015	6/10/2016	None
ISL12029AIB27Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029AIV27Z	6/10/2015	12/10/2015	6/10/2016	None
ISL12029AIV27Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IB27AZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IB27AZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IB27Z	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IB27Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IB30AZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IB30AZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IBAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IBAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IV27AZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IV27AZ-T	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL12029IV27Z	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IV27Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IV30AZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IV30AZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IVAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IVAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12029IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12030IBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12030IBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12032IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12032IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12057IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12058IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12059IBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12059IBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL12082IUZ	6/10/2015	12/10/2015	6/10/2016	None
ISL12082IUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL1208W	6/10/2015	12/10/2015	6/10/2016	None
ISL1220IUZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1532AIRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1532AIRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL1532AIRZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL1532AIVEZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1532AIVEZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL1532AIVEZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL1532IRZ	6/10/2015	12/10/2015	6/10/2016	ISL1533IRZ
ISL1532IRZ-T13	6/10/2015	12/10/2015	6/10/2016	ISL1533IRZ-T13
ISL1532IRZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL1533IRZ-T13
ISL1532IVEZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1532IVEZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL1532IVEZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL1533IVEZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1533IVEZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL1534IVEZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1534IVEZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL1535AIRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1535AIRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL1535IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1535IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL1535IVEZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1535IVEZR5317	6/10/2015	12/10/2015	6/10/2016	None
ISL1535IVEZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL1535IVEZ-T13R5317	6/10/2015	12/10/2015	6/10/2016	None
ISL1539IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1539IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL1539IRZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL1557AIUEZ	6/10/2015	12/10/2015	6/10/2016	None
ISL1557AIUEZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL21007CFB830Z	6/10/2015	12/10/2015	6/10/2016	ISL21007CFB825Z-TK
ISL21007CFB830Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL21007CFB825Z-TK
ISL21007DFB820Z	6/10/2015	12/10/2015	6/10/2016	ISL21007CFB825Z-TK
ISL21007DFB820Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL21007CFB825Z-TK
ISL21007DFB830Z	6/10/2015	12/10/2015	6/10/2016	ISL21007CFB825Z-TK
ISL21007DFB830Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL21007CFB825Z-TK
ISL21009DFB862Z	6/10/2015	12/10/2015	6/10/2016	ISL21009BFB850Z-TK
ISL21009DFB862Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL21009BFB850Z-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL2100AABZ	6/10/2015	12/10/2015	6/10/2016	HIP2100IBZ
ISL2100AABZ-T	6/10/2015	12/10/2015	6/10/2016	HIP2100IBZT
ISL2100AAR3Z	6/10/2015	12/10/2015	6/10/2016	None
ISL2100AAR3Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL21070DIH306Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL21070CIH325Z-TK
ISL22102IV20Z	6/10/2015	12/10/2015	6/10/2016	None
ISL22102IV20Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL22316UFRT10Z	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22316UFRT10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22316UFU10Z	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22316UFU10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22317TFRTZ	6/10/2015	12/10/2015	6/10/2016	ISL22317WFRTZ-TK
ISL22317TFRTZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL22317WFRTZ-TK
ISL22317UFRTZ	6/10/2015	12/10/2015	6/10/2016	ISL22317WFRTZ-TK
ISL22317UFRTZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL22317WFRTZ-TK
ISL22317UFRTZTKS2568	6/10/2015	12/10/2015	6/10/2016	ISL22317WFRTZ-TK
ISL22323UFR16Z	6/10/2015	12/10/2015	6/10/2016	ISL22323TFV14Z-TK
ISL22323UFR16Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22323TFV14Z-TK
ISL22323UFV14Z	6/10/2015	12/10/2015	6/10/2016	ISL22323TFV14Z-TK
ISL22323UFV14Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22323TFV14Z-TK
ISL22323WFR16Z	6/10/2015	12/10/2015	6/10/2016	ISL22323TFV14Z-TK
ISL22323WFR16Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22323TFV14Z-TK
ISL22323WV14Z	6/10/2015	12/10/2015	6/10/2016	ISL22323TFV14Z-TK
ISL22323WV14Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22323TFV14Z-TK
ISL22326UFR16Z	6/10/2015	12/10/2015	6/10/2016	ISL22326WFR16Z-TK
ISL22326UFR16Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22326WFR16Z-TK
ISL22326UFV14Z	6/10/2015	12/10/2015	6/10/2016	ISL22326WFR16Z-TK
ISL22326UFV14Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22326WFR16Z-TK
ISL22343TFR20Z	6/10/2015	12/10/2015	6/10/2016	ISL22343WFR20Z-TK
ISL22343TFR20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22343WFR20Z-TK
ISL22343TFV20Z	6/10/2015	12/10/2015	6/10/2016	ISL22343WFR20Z-TK
ISL22343TFV20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22343WFR20Z-TK
ISL22343UFR20Z	6/10/2015	12/10/2015	6/10/2016	ISL22343WFR20Z-TK
ISL22343UFR20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22343WFR20Z-TK
ISL22343UFV20Z	6/10/2015	12/10/2015	6/10/2016	ISL22343WFR20Z-TK
ISL22343UFV20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22343WFR20Z-TK
ISL22414UFU10Z	6/10/2015	12/10/2015	6/10/2016	ISL22414TFU10Z-TK
ISL22414UFU10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22414TFU10Z-TK
ISL22414WV10Z	6/10/2015	12/10/2015	6/10/2016	ISL22414TFU10Z-TK
ISL22414WV10Z-T7A	6/10/2015	12/10/2015	6/10/2016	ISL22414TFU10Z-TK
ISL22416UFRT10Z	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22416UFRT10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22416UFU10Z	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22416UFU10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22416WFRT10Z	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22416WFRT10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22416WV10Z	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22416WV10ZS2426	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22416WV10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22416WV10ZTS2568	6/10/2015	12/10/2015	6/10/2016	ISL22316WFRT10Z-TK
ISL22424TFR16Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22424TFR16Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22424TFV14Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22424TFV14Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22424UFR16Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22424UFR16Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL22424UFV14Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22424UFV14Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22426UFR16Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22426UFR16Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22426UFV14Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22426UFV14Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22426WFR16Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22426WFR16Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22426WV14Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22426WV14Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444TFR20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444TFR20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444TFV20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444TFV20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444UFR20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444UFR20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444UFV20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444UFV20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444WFR20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444WFR20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444WV20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22444WV20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22446UFRT20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22446UFRT20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22446UFV20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22446UFV20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22446WFRT20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22446WFRT20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22446WV20Z	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22446WV20Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22424WFR16Z-TK
ISL22511UF88Z	6/10/2015	12/10/2015	6/10/2016	ISL22511WFRU10Z-TK
ISL22511UF88Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22511WFRU10Z-TK
ISL22511UFRU10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22511WFRU10Z-TK
ISL22512WFRU10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL22512WFB8Z-TK
ISL23315UFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23315TFUZ-TK
ISL23315UFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23315TFUZ-TK
ISL23315UFUZ	6/10/2015	12/10/2015	6/10/2016	ISL23315TFUZ-TK
ISL23315UFUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23315TFUZ-TK
ISL23315UFUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23315TFUZ-TK
ISL23315WFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23315TFUZ-TK
ISL23315WFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23315TFUZ-TK
ISL23325UFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23325UFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23325UFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23325UFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23325UFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23328UFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23328TFRUZ-TK
ISL23328UFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23328TFRUZ-TK
ISL23328UFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23328TFRUZ-TK
ISL23328UFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23328TFRUZ-TK
ISL23328UFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23328TFRUZ-TK
ISL23345TFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345TFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345TFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345TFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345TFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345TFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL23345UFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345UFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345UFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345UFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345UFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345UFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345WFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345WFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345WFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345WVZ	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345WVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23345WVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23325TFRUZ-TK
ISL23348TFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348TFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348TFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348TFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348TFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348TFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348UFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348UFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348UFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348UFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348UFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348UFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348WFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348WFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348WFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348WVZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348WVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23348WVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23415UFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23415WFUZ-TK
ISL23415UFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23415WFUZ-TK
ISL23415UFUZ	6/10/2015	12/10/2015	6/10/2016	ISL23415WFUZ-TK
ISL23415UFUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23415WFUZ-TK
ISL23415UFUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23415WFUZ-TK
ISL23415WFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23415WFUZ-TK
ISL23415WFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23415WFUZ-TK
ISL23418UFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23418TFRUZ-TK
ISL23418UFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23418TFRUZ-TK
ISL23418WFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23418TFRUZ-TK
ISL23418WFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23418TFRUZ-TK
ISL23425UFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFRUZ-TK
ISL23425UFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFRUZ-TK
ISL23425UFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFRUZ-TK
ISL23425UFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFRUZ-TK
ISL23425UFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFRUZ-TK
ISL23428UFRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23428UFRUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23428UFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23428UFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23428UFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23445TFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445TFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445TFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445TFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445TFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445TFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL23445UFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445UFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445UFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445UFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445UFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445UFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445WFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445WFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445WFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445WVZ	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445WVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23445WVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23425TFVZ-TK
ISL23448TFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448TFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448TFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448TFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448TFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448TFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448UFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448UFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448UFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448UFVZ	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448UFVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448UFVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448WFRZ	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448WFRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448WFRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448WVZ	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448WVZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23448WVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL23428TFRUZ-TK
ISL23511UFB8Z	6/10/2015	12/10/2015	6/10/2016	None
ISL23511UFB8Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL23511UFRU10Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL23511WFRU10Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL23512WFRU10Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL23710UIU10Z	6/10/2015	12/10/2015	6/10/2016	X9015US8IZT1
ISL23710UIU10Z-T	6/10/2015	12/10/2015	6/10/2016	X9015US8IZT1
ISL23710WIU10Z	6/10/2015	12/10/2015	6/10/2016	X9015US8IZT1
ISL23710WIU10Z-T	6/10/2015	12/10/2015	6/10/2016	X9015US8IZT1
ISL23711UIU10Z	6/10/2015	12/10/2015	6/10/2016	None
ISL23711UIU10Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL23711WIU10Z	6/10/2015	12/10/2015	6/10/2016	None
ISL23711WIU10Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL24002IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24002IRTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24005IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24005IRTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24007IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24007IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24010IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24010IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL24011IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24011IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL24102IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24102IRTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24103IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24103IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL24105IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24105IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24111IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24111IRTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24821IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24821IRTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24822IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24822IRTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24832IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24832IRZR5513	6/10/2015	12/10/2015	6/10/2016	None
ISL24832IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24832IRZ-T13R5513	6/10/2015	12/10/2015	6/10/2016	None
ISL24835IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24835IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24837IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24837IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24867IRXZ	6/10/2015	12/10/2015	6/10/2016	None
ISL24867IRXZR5560	6/10/2015	12/10/2015	6/10/2016	None
ISL24867IRXZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL24867IRXZT13R5560	6/10/2015	12/10/2015	6/10/2016	None
ISL25700FRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL25700FRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL25700FRUZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL26310FBZ	6/10/2015	12/10/2015	6/10/2016	ISL26320FBZ
ISL26310FBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL26320FBZ
ISL26310FBZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL26320FBZ
ISL26311FBZ	6/10/2015	12/10/2015	6/10/2016	ISL26321FBZ
ISL26311FBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL26321FBZ
ISL26311FBZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL26321FBZ
ISL28107FBZ	6/10/2015	12/10/2015	6/10/2016	ISL28107FUZ-T7
ISL28107FBZ-T13	6/10/2015	12/10/2015	6/10/2016	ISL28107FUZ-T7
ISL28107FBZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28107FUZ-T7
ISL28107FBZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL28107FUZ-T7
ISL28107FRTZ	6/10/2015	12/10/2015	6/10/2016	ISL28107FUZ-T7
ISL28107FRTZ-T13	6/10/2015	12/10/2015	6/10/2016	ISL28107FUZ-T7
ISL28107FRTZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28107FUZ-T7
ISL28107FRTZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL28107FUZ-T7
ISL28127FBZ	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FBZ-T13	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FBZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FBZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FRTBZ	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FRTBZ-T13	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FRTBZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FRTBZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FUBZ	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FUBZ-T13	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FUBZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FUBZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FUZ	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FUZ-T13	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FUZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28127FUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL28127FRTZ-T13
ISL28133FRUZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28133FHZ-T7
ISL28156FBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL28156FBZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL28156FHZ-T7	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL28166FHZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL28190FHZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL28190FRUZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL28213FHZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28213FBZ-T7
ISL28213FHZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL28213FBZ-T7
ISL28214FHZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28214FBZ-T7
ISL28214FHZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL28214FBZ-T7
ISL28258FBZ	6/10/2015	12/10/2015	6/10/2016	ISL28158FBZ-T7
ISL28258FBZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28158FBZ-T7
ISL28258FUZ	6/10/2015	12/10/2015	6/10/2016	ISL28158FBZ-T7
ISL28258FUZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL28158FBZ-T7
ISL28271FAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL28271FAZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL28273FAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL28273FAZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL28417W	6/10/2015	12/10/2015	6/10/2016	None
ISL28617FVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL28617FVZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL28617FVZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL28617FVZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL29007IROZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL29008IROZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL29010IROZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL3035EIRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL3035EIRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL3035EIRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL3036EIRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL3036EIRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL3036EIRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL3036EIRZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL3036EIRZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL31472EIPZ	6/10/2015	12/10/2015	6/10/2016	ISL32472EIBZ
ISL31483EIBZ	6/10/2015	12/10/2015	6/10/2016	ISL32483EIBZ
ISL31483EIBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL32483EIBZ-T
ISL31483EIBZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL32483EIBZ-T7A
ISL31490EIRTZ	6/10/2015	12/10/2015	6/10/2016	ISL32490EIBZ
ISL31490EIRTZ-T	6/10/2015	12/10/2015	6/10/2016	ISL32490EIBZ-T
ISL31490EIRTZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL32490EIBZ-T7A
ISL31490EIUZ	6/10/2015	12/10/2015	6/10/2016	ISL32490EIUZ
ISL31490EIUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL32490EIUZ-T
ISL31490EIUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL32490EIUZ-T7A
ISL31492EIPZ	6/10/2015	12/10/2015	6/10/2016	ISL32492EIUZ
ISL31492EIUZ	6/10/2015	12/10/2015	6/10/2016	ISL32492EIUZ
ISL31492EIUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL32492EIUZ-T
ISL31492EIUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL32492EIUZ-T7A
ISL31493EIBZ	6/10/2015	12/10/2015	6/10/2016	ISL32493EIBZ
ISL31493EIBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL32493EIBZ-T
ISL31493EIBZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL32493EIBZ-T7A
ISL31493EIUZ	6/10/2015	12/10/2015	6/10/2016	ISL32493EIUZ
ISL31493EIUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL32493EIUZ-T
ISL31493EIUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL32493EIUZ-T7A
ISL31495EIUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL32495EIUZ-T7A
ISL31496EIUZ	6/10/2015	12/10/2015	6/10/2016	ISL32496EIUZ
ISL31496EIUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL32496EIUZ-T
ISL31496EIUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL32496EIUZ-T7A
ISL31498EIUZ	6/10/2015	12/10/2015	6/10/2016	ISL32498EIUZ
ISL31498EIUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL32498EIUZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL31498EIUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL32498EIUZ-T7A
ISL3178AEMBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL3178AEMBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL43121IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43120IHZ-T
ISL43122IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43120IHZ-T
ISL43142IBZ	6/10/2015	12/10/2015	6/10/2016	ISL43120IHZ-T
ISL43142IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43120IHZ-T
ISL43142IVZ	6/10/2015	12/10/2015	6/10/2016	ISL43120IHZ-T
ISL43142IVZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43120IHZ-T
ISL43144IRZ	6/10/2015	12/10/2015	6/10/2016	ISL43120IHZ-T
ISL43144IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43120IHZ-T
ISL43841IRZ	6/10/2015	12/10/2015	6/10/2016	ISL43840IRZ-T
ISL43841IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43840IRZ-T
ISL43L111IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L120IRZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L120IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L120IUZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L120IUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L121IRZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L121IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L121IUZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L121IUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L122IRZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L122IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L122IUZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L122IUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L122IUZ-TS2568	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L220IRZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L220IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L410IRZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L410IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L410IUZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L410IUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L710IUZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L710IUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L712IRZ	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL43L712IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL43L210IHZ-T
ISL45041IRZR5486	6/10/2015	12/10/2015	6/10/2016	None
ISL45041IRZ-TR5486	6/10/2015	12/10/2015	6/10/2016	None
ISL5120CBZ	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5120CBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5120IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5120IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5121CBZ	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5121CBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5121IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5121IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5121IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5122CBZ	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5122CBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5122IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5122IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5122IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5123CBZ	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5123CBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5123IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5123IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL5123IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL5120IHZ-T
ISL5216W	6/10/2015	12/10/2015	6/10/2016	None
ISL5217W	6/10/2015	12/10/2015	6/10/2016	None
ISL5239KI	6/10/2015	12/10/2015	6/10/2016	None
ISL5239KIZ	6/10/2015	12/10/2015	6/10/2016	None
ISL53562IAR5261	6/10/2015	12/10/2015	6/10/2016	None
ISL53582AWS2571	6/10/2015	12/10/2015	6/10/2016	None
ISL54000IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54000IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54001IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54001IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54002IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54002IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54003IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54003IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54004IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54004IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54005IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54005IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54006IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54006IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54047IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54048IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54049IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54054IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54054IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54055IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54056IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54057IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54066IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54066IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54066IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54105CRZ	6/10/2015	12/10/2015	6/10/2016	ISL54105ACRZ
ISL54106CRZ	6/10/2015	12/10/2015	6/10/2016	ISL54106ACRZ
ISL54205AIRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54205AIRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54205AIRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54205BIRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54205BIRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54205BIRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54206AIRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54206AIRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54206AIRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54206IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54206IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54206IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54207IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54207IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54207IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54208IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54208IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54208IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54209IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54209IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54209IRU1Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54209IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54209IRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL54210IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54212IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54212IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54212IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54213IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54213IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54213IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54215IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54226IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54226IRTZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL54226IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54226IRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL54228IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54228IRTZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL54228IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54228IRUZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL54230IIZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54230IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54230IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54300IRZR5258	6/10/2015	12/10/2015	6/10/2016	None
ISL54300IRZ-TR5258	6/10/2015	12/10/2015	6/10/2016	None
ISL54302IRZ	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54302IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54400IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54400IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54400IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54401IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54401IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54401IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54402IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54402IRUZ-TS2038	6/10/2015	12/10/2015	6/10/2016	None
ISL54402IRUZ-TS2687	6/10/2015	12/10/2015	6/10/2016	None
ISL54402IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL54402IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54415IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54416IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54417IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL54500IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54500IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54501IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54501IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54502IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54502IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54503IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54503IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54504IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54504IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54505IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL54505IRUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL54050IRUZ-T
ISL55020IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL55020IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL55036IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL55036IRTZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL55119IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL55119IRTZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL55141IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL55141IRZ-T	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL55141IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL55141IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL55142IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL55142IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL55142IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL55142IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL55190IBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL55190IBZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL55290IUZ	6/10/2015	12/10/2015	6/10/2016	None
ISL55290IUZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL5571AIBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5571AIBZS2693	6/10/2015	12/10/2015	6/10/2016	None
ISL5571AIBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL5571AIBZ-TS2693	6/10/2015	12/10/2015	6/10/2016	None
ISL5627INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5629/2INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5629INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5727INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5729/2INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5729INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5757IBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5761/2IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5761IAZ
ISL5761IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5761IAZ
ISL5827INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5829/2INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5829INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL58334CIZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL58334CIZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL58344CIZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL58344CIZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL5857IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5857IAZ
ISL5861/2IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5861IAZ
ISL5861IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5861IAZ
ISL59112IEZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL59110IEZ-T7
ISL59114IRUZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59115IRUZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL59116IIZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL59119IBZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL59123IIZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL5927INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5929INZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59421IUZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59421IUZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL59421IUZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL59441IAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59441IAZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL59441IAZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL59442IBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59442IBZS2714	6/10/2015	12/10/2015	6/10/2016	None
ISL59442IBZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL59442IBZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL59442IBZ-T7S2714	6/10/2015	12/10/2015	6/10/2016	None
ISL59444IBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59444IBZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL59444IBZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL59448IAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59448IAZ-T7	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL59448IAZ-T7S2490	6/10/2015	12/10/2015	6/10/2016	None
ISL59481IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59481IRZ-T13	6/10/2015	12/10/2015	6/10/2016	None
ISL59530IKZ	6/10/2015	12/10/2015	6/10/2016	None
ISL5957IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5957IAZ
ISL5961/2IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5961/2IAZ
ISL5961IBZ	6/10/2015	12/10/2015	6/10/2016	ISL5961IAZ
ISL59831IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59831IRTZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL59832IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59921IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59921IRZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL59922IRZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL59923IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL59923IRZ-T7	6/10/2015	12/10/2015	6/10/2016	None
ISL6115CBZAR5217	6/10/2015	12/10/2015	6/10/2016	ISL6115CBZA-T
ISL6115CBZAS2695	6/10/2015	12/10/2015	6/10/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S	6/10/2015	12/10/2015	6/10/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S1	6/10/2015	12/10/2015	6/10/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S2	6/10/2015	12/10/2015	6/10/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S3	6/10/2015	12/10/2015	6/10/2016	ISL6115CBZA-T
ISL6115CBZA-TS2490S4	6/10/2015	12/10/2015	6/10/2016	ISL6115CBZA-T
ISL6115CBZA-TS2568	6/10/2015	12/10/2015	6/10/2016	ISL6115CBZA-T
ISL6115CBZA-TS2695	6/10/2015	12/10/2015	6/10/2016	ISL6115CBZA-T
ISL6116CBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6116CBZAS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL6116CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6116CBZA-TS2490S	6/10/2015	12/10/2015	6/10/2016	None
ISL6116CBZA-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL6116CBZA-TS2705	6/10/2015	3/10/2016	3/10/2017	None
ISL6117CBZAR5217	6/10/2015	12/10/2015	6/10/2016	ISL6117CBZA
ISL6117CBZA-TR5217	6/10/2015	12/10/2015	6/10/2016	ISL6117CBZA-T
ISL6117CBZA-TS2490S	6/10/2015	12/10/2015	6/10/2016	ISL6117CBZA-T
ISL6118HIBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6118HIBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6118HIBZA-TS2705	6/10/2015	3/10/2016	3/10/2017	None
ISL6119HIBZA-TS2568	6/10/2015	12/10/2015	6/10/2016	ISL6119HIBZA-T
ISL6119LIBZA-TS2715	6/10/2015	12/10/2015	6/10/2016	ISL6119LIBZA-T
ISL6120CBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6120CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6140IB-T	6/10/2015	12/10/2015	6/10/2016	ISL6140IBZ-T
ISL6142CBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6142CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6142IBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6142IBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6144IVZA-TS2568	6/10/2015	12/10/2015	6/10/2016	ISL6144IVZA-T
ISL6150CB	6/10/2015	12/10/2015	6/10/2016	ISL6150CBZ
ISL6150IB-T	6/10/2015	12/10/2015	6/10/2016	ISL6150IBZ-T
ISL6151CBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6151CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6151IBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6151IBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6152CBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6152CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6152IBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6152IBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6160CBZA	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6160CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6161IBZA	6/10/2015	12/10/2015	6/10/2016	ISL6161CBZA
ISL6161IBZA-T	6/10/2015	12/10/2015	6/10/2016	ISL6161CBZA-T
ISL6207HBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6216CAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6217ACVZA-TS2490	6/10/2015	12/10/2015	6/10/2016	None
ISL6217ACVZ-TS2490	6/10/2015	12/10/2015	6/10/2016	None
ISL6223CAZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6223CAZAR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6223CAZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6223CAZA-TR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6224CAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6224CAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6225CAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6225CAZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6225CAZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6225CAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6225CAZ-TR5189	6/10/2015	12/10/2015	6/10/2016	None
ISL6225CAZ-TS2568	6/10/2015	12/10/2015	6/10/2016	None
ISL6237IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL62381CHRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL62381CHRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL62382CHRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL62382CHRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL62391CHRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL62391CHRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL62391CIRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL62391CIRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6251AHAZR5283	6/10/2015	12/10/2015	6/10/2016	None
ISL6251AHAZ-TR5283	6/10/2015	12/10/2015	6/10/2016	None
ISL6252AHAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6252AHAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6252AHRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6252AHRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6252HAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6252HAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6252HRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6252HRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6255HAZR5283	6/10/2015	12/10/2015	6/10/2016	None
ISL6255HAZ-TR5283	6/10/2015	12/10/2015	6/10/2016	None
ISL6255HRZR5283	6/10/2015	12/10/2015	6/10/2016	None
ISL6255HRZ-TR5283	6/10/2015	12/10/2015	6/10/2016	None
ISL6266HRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6266HRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6269CRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6269CRZR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6269CRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6269CRZ-TR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6269IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6271ACRZR5463	6/10/2015	12/10/2015	6/10/2016	None
ISL6271ACRZ-TR5463	6/10/2015	12/10/2015	6/10/2016	None
ISL6273IRZS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL6273IRZ-TS2687	6/10/2015	12/10/2015	6/10/2016	None
ISL6273IRZ-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL6274AIRZ-TR5256	6/10/2015	12/10/2015	6/10/2016	None
ISL62873HRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6292DCRZ	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6292DCRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6293-2CRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6293-2CRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6294AIRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6296ADHZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6296DHZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6296DHZ-TR5287	6/10/2015	12/10/2015	6/10/2016	None
ISL6296DRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6296DRZ-TR5266	6/10/2015	12/10/2015	6/10/2016	None
ISL6296W	6/10/2015	12/10/2015	6/10/2016	None
ISL6297CRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6297CRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6299AIRZ	6/10/2015	12/10/2015	6/10/2016	ISL9214AIRZ
ISL6299AIRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9214AIRZ
ISL6299AIRZ-TS2697	6/10/2015	12/10/2015	6/10/2016	ISL9214AIRZ
ISL6299IRZ	6/10/2015	12/10/2015	6/10/2016	ISL9214AIRZ
ISL6299IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9214AIRZ
ISL6299IRZ-TS2688	6/10/2015	12/10/2015	6/10/2016	ISL9214AIRZ
ISL6312CRZ-TR5453	6/10/2015	12/10/2015	6/10/2016	None
ISL6313BCRZ-TS2568	6/10/2015	12/10/2015	6/10/2016	ISL6313BCRZ-T
ISL6313BCRZ-TS2704	6/10/2015	12/10/2015	6/10/2016	ISL6313BCRZ-T
ISL6314CRZ-TR5453	6/10/2015	12/10/2015	6/10/2016	None
ISL6328CRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6328CRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6341CRZ-TS2568	6/10/2015	12/10/2015	6/10/2016	ISL6341BIRZ-T
ISL6364ACRZ-TS2490	6/10/2015	12/10/2015	6/10/2016	None
ISL6401CB	6/10/2015	12/10/2015	6/10/2016	ISL6401CBZ
ISL6401CB-T	6/10/2015	12/10/2015	6/10/2016	ISL6401CBZ-T
ISL6401CRZ	6/10/2015	12/10/2015	6/10/2016	ISL6401CBZ
ISL6401CRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6401CBZ-T
ISL6401CRZ-TS2705	6/10/2015	3/10/2016	3/10/2017	ISL6401CBZ-T
ISL6406IBZ	6/10/2015	12/10/2015	6/10/2016	ISL6406IVZ
ISL6406IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6406IVZ-T
ISL6406XC	6/10/2015	12/10/2015	6/10/2016	None
ISL6410AIUZ-TKS2695	6/10/2015	12/10/2015	6/10/2016	ISL6410AIUZ
ISL6412IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6412IRZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL6416IAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6416IAZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL6422BEVEZ	6/10/2015	12/10/2015	6/10/2016	ISL6422BERZ
ISL6422BEVEZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6422BERZ-T
ISL6439AIBZ-TS2705	6/10/2015	3/10/2016	3/10/2017	ISL6439AIBZ-T
ISL6439CBZ	6/10/2015	12/10/2015	6/10/2016	ISL6439IBZ
ISL6439CBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6439IBZ-T
ISL6442IAZ-TKS2568	6/10/2015	12/10/2015	6/10/2016	ISL6442IAZ-TK
ISL6442IAZ-TKS2715	6/10/2015	12/10/2015	6/10/2016	ISL6442IAZ-TK
ISL6443AIVZ	6/10/2015	12/10/2015	6/10/2016	ISL6443AIRZ
ISL6443AIVZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL6443AIRZ-TK
ISL6444CAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6444CAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6504CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6504CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6506BIBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6506BIBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6506CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6506CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6520ACBZR5194	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6520ACBZR5217	6/10/2015	12/10/2015	6/10/2016	None
ISL6520ACBZ-TR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6520ACBZ-TR5217	6/10/2015	12/10/2015	6/10/2016	None
ISL6520AIBZS2698	6/10/2015	12/10/2015	6/10/2016	None
ISL6520AIBZ-TS2698	6/10/2015	12/10/2015	6/10/2016	None
ISL6520BCBZR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6520BCBZ-TR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6520CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6520CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6520IBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6520IBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6521CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6521CBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6521CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6521CBZS2698	6/10/2015	12/10/2015	6/10/2016	None
ISL6521CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6521CBZ-TS2568	6/10/2015	12/10/2015	6/10/2016	None
ISL6521CBZ-TS2698	6/10/2015	12/10/2015	6/10/2016	None
ISL6521IBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6521IBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6522BCBZ	6/10/2015	12/10/2015	6/10/2016	ISL6522BIBZ
ISL6522BCBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6522BIBZ-T
ISL6522BCRZ	6/10/2015	12/10/2015	6/10/2016	ISL6535CRZ-T
ISL6522BCRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6535CRZ-T
ISL6522BIBZS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522BIBZ
ISL6522BIBZ-TS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522BIBZ-T
ISL6522BIRZR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522BIRZ
ISL6522BIRZS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522BIRZ
ISL6522BIRZ-TKS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522BIRZ-TK
ISL6522BIRZ-TS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522BIRZ-T
ISL6522CBZA	6/10/2015	12/10/2015	6/10/2016	ISL6522CBZ
ISL6522CBZAR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522CBZ
ISL6522CBZA-T	6/10/2015	12/10/2015	6/10/2016	ISL6522CBZ-T
ISL6522CBZA-TR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522CBZ-T
ISL6522CBZR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522CBZ
ISL6522CBZ-TS2462	6/10/2015	12/10/2015	6/10/2016	ISL6522CBZ-T
ISL6522CBZ-TS2713	6/10/2015	12/10/2015	6/10/2016	ISL6522CBZ-T
ISL6522CRZR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522CRZ
ISL6522CRZS2462	6/10/2015	12/10/2015	6/10/2016	ISL6522CRZ
ISL6522CRZ-TR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522CRZ-T
ISL6522CVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6522CVZR5190	6/10/2015	12/10/2015	6/10/2016	None
ISL6522CVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6522CVZ-TR5190	6/10/2015	12/10/2015	6/10/2016	None
ISL6522CVZ-TS2462	6/10/2015	12/10/2015	6/10/2016	None
ISL6522IBZR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522IBZ
ISL6522IBZS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522IBZ
ISL6522IBZ-TR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522IBZ-T
ISL6522IBZ-TS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522IBZ-T
ISL6522IRZR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522IRZ
ISL6522IRZS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522IRZ
ISL6522IRZ-TKR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522IRZ-TK
ISL6522IRZ-TKS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522IRZ-TK
ISL6522IRZ-TR5190	6/10/2015	12/10/2015	6/10/2016	ISL6522IRZ-T
ISL6522IRZ-TS2698	6/10/2015	12/10/2015	6/10/2016	ISL6522IRZ-T
ISL6522IVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6522IVZS2698	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6522IVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6522IVZ-TS2698	6/10/2015	12/10/2015	6/10/2016	None
ISL6523CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6523CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6524ACBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6524ACBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6524ACBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6526ACBZ	6/10/2015	12/10/2015	6/10/2016	ISL6526AIRZ
ISL6526ACBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6526AIRZ-T
ISL6526AIRZ-TKR5426	6/10/2015	12/10/2015	6/10/2016	ISL6526AIRZ-TK
ISL6526CBZR5217	6/10/2015	12/10/2015	6/10/2016	ISL6526CBZ-T
ISL6526CBZ-TR5217	6/10/2015	12/10/2015	6/10/2016	ISL6526CBZ-T
ISL6526CRZ	6/10/2015	12/10/2015	6/10/2016	ISL6526IRZ
ISL6526CRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6526IRZ-T
ISL6526IBZR5146	6/10/2015	12/10/2015	6/10/2016	ISL6526IBZ
ISL6526IBZ-TR5146	6/10/2015	12/10/2015	6/10/2016	ISL6526IBZ-T
ISL6527ACRZ	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ
ISL6527ACRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ-T
ISL6527ACRZ-TS2705	6/10/2015	3/10/2016	3/10/2017	ISL6527ACBZ-T
ISL6527AIRZ	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ
ISL6527AIRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ-T
ISL6527CRZ	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ
ISL6527CRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ-T
ISL6527IBZ	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ
ISL6527IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ-T
ISL6527IRZ	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ
ISL6527IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6527ACBZ-T
ISL6528CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6528CBZR5217	6/10/2015	12/10/2015	6/10/2016	None
ISL6528CBZS2698	6/10/2015	12/10/2015	6/10/2016	None
ISL6528CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6528CBZ-TR5217	6/10/2015	12/10/2015	6/10/2016	None
ISL6528CBZ-TS2698	6/10/2015	12/10/2015	6/10/2016	None
ISL6529CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6529CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6530CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6530CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6532CCRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6532CCRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6545CBZ-TR5453	6/10/2015	12/10/2015	6/10/2016	None
ISL6545IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6545IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6548CRZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6548CRZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6549CAZAR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6549CBZR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6549CBZ-TR5194	6/10/2015	12/10/2015	6/10/2016	None
ISL6551ABZ	6/10/2015	12/10/2015	6/10/2016	ISL6551IBZ
ISL6551ABZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6551IBZ-T
ISL6552CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6552CBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6552CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6552CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6552CBZ-TS2462	6/10/2015	12/10/2015	6/10/2016	None
ISL6552CRZ-TS2462	6/10/2015	12/10/2015	6/10/2016	None
ISL6553CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6553CBZA	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6553CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6553CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6554CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6554CBZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6554CBZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6554CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6554CBZ-TR5165	6/10/2015	12/10/2015	6/10/2016	None
ISL6556ACBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6556ACBZR5208	6/10/2015	12/10/2015	6/10/2016	None
ISL6556ACBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6556ACBZ-TR5208	6/10/2015	12/10/2015	6/10/2016	None
ISL6556BCBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6556BCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6557ACBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6557ACBZR5217	6/10/2015	12/10/2015	6/10/2016	None
ISL6557ACBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6557ACBZ-TR5217	6/10/2015	12/10/2015	6/10/2016	None
ISL6558CBZAR5284	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA-T
ISL6558CBZA-TR5284	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA-T
ISL6558CBZA-TS2462	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA-T
ISL6558CBZA-TS2490S	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA-T
ISL6558CBZA-TS2490S1	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA-T
ISL6558CBZA-TS2490S2	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA-T
ISL6558CBZA-TS2490S3	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA-T
ISL6558CBZA-TS2705	6/10/2015	3/10/2016	3/10/2017	ISL6558CBZA-T
ISL6558CRZA	6/10/2015	12/10/2015	6/10/2016	ISL6558CRZ
ISL6558CRZA-T	6/10/2015	12/10/2015	6/10/2016	ISL6558CRZ-T
ISL6558CRZR5284	6/10/2015	12/10/2015	6/10/2016	ISL6558CRZ-T
ISL6558CRZ-TR5284	6/10/2015	12/10/2015	6/10/2016	ISL6558CRZ-T
ISL6558IBZ	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA
ISL6558IBZR5284	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA
ISL6558IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA-T
ISL6558IBZ-TR5284	6/10/2015	12/10/2015	6/10/2016	ISL6558CBZA-T
ISL6558IRZR5240	6/10/2015	12/10/2015	6/10/2016	ISL6558IRZ-T
ISL6558IRZR5284	6/10/2015	12/10/2015	6/10/2016	ISL6558IRZ
ISL6558IRZ-TKR5240	6/10/2015	12/10/2015	6/10/2016	ISL6558IRZ-TK
ISL6558IRZ-TR5240	6/10/2015	12/10/2015	6/10/2016	ISL6558IRZ-T
ISL6558IRZ-TR5284	6/10/2015	12/10/2015	6/10/2016	ISL6558IRZ-T
ISL6559CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6559CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6559CRZ-TS2705	6/10/2015	3/10/2016	3/10/2017	None
ISL6560CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6560CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6561CRZR5208	6/10/2015	12/10/2015	6/10/2016	None
ISL6561CRZR5284	6/10/2015	12/10/2015	6/10/2016	None
ISL6561CRZ-TR5208	6/10/2015	12/10/2015	6/10/2016	None
ISL6561CRZ-TR5284	6/10/2015	12/10/2015	6/10/2016	None
ISL6565ACBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6565ACBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6565ACVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6565ACVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6565BCBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6565BCBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6565BCVZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6565BCVZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6569ACBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6569ACBZ-T	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6569CBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6569CBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6594BCBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6594ACRZ-T
ISL6596CBZ	6/10/2015	12/10/2015	6/10/2016	ISL6596CRZ
ISL6596CBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6596CRZ-T
ISL6596CRZ-TS2568	6/10/2015	12/10/2015	6/10/2016	ISL6596CRZ-T
ISL6596IBZ	6/10/2015	12/10/2015	6/10/2016	ISL6596CRZ
ISL6596IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6596CRZ-T
ISL6598DRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6598DRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6612CBZ-TR5238	6/10/2015	12/10/2015	6/10/2016	ISL6612CBZ
ISL6700IBZ-TS2568	6/10/2015	12/10/2015	6/10/2016	ISL6700IBZ-T
ISL6700IW	6/10/2015	12/10/2015	6/10/2016	None
ISL6721AV-T	6/10/2015	12/10/2015	6/10/2016	ISL6721AVZ-T
ISL6723AABZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6723AABZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6753AAZAR5388	6/10/2015	12/10/2015	6/10/2016	ISL6753AAZA
ISL6753AAZA-TR5388	6/10/2015	12/10/2015	6/10/2016	ISL6753AAZA-T
ISL6755AAZA	6/10/2015	12/10/2015	6/10/2016	None
ISL6755AAZA-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6842IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6842IBZ-T
ISL6842IUZ	6/10/2015	12/10/2015	6/10/2016	ISL6842IBZ
ISL6842IUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6842IBZ-T
ISL6842IUZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL6842IBZ-T
ISL6843IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL6843IBZ-T
ISL6843IU-T	6/10/2015	12/10/2015	6/10/2016	ISL6843IUZ-T
ISL6881IAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6881IAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL6884IAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL6884IAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL78200AVEZ-TR5303	6/10/2015	6/10/2016	#####	ISL78201AVEZ-TR5303
ISL78205AVEZ-TR5303	6/10/2015	6/10/2016	#####	ISL78206AVEZ-TR5303
ISL78211ARZ	6/10/2015	6/10/2016	#####	None
ISL78211ARZ-T	6/10/2015	6/10/2016	#####	None
ISL78211ARZ-TR5303	6/10/2015	6/10/2016	#####	None
ISL78223AAZ	6/10/2015	6/10/2016	#####	None
ISL78223AAZ-T	6/10/2015	6/10/2016	#####	None
ISL8009IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL8009AIRZ-T
ISL80101R18Z	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ
ISL80101R18Z-T	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ-T
ISL80101R18Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ-TK
ISL80101R25Z	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ
ISL80101R25Z-T	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ-T
ISL80101R25Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ-TK
ISL80101R33Z	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ
ISL80101R33Z-T	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ-T
ISL80101R33Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ-TK
ISL80101R50Z	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ
ISL80101R50Z-T	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ-T
ISL80101R50Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL80101RAJZ-TK
ISL80102R18Z	6/10/2015	12/10/2015	6/10/2016	ISL80102RAJZ
ISL80102R18Z-T	6/10/2015	12/10/2015	6/10/2016	ISL80102RAJZ-T
ISL80102R18Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL80102RAJZ-TK
ISL80102R25Z	6/10/2015	12/10/2015	6/10/2016	ISL80102RAJZ
ISL80102R25Z-T	6/10/2015	12/10/2015	6/10/2016	ISL80102RAJZ-T
ISL80102R25Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL80102RAJZ-TK
ISL80103R18Z	6/10/2015	12/10/2015	6/10/2016	ISL80103RAJZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL80103IR18Z-T	6/10/2015	12/10/2015	6/10/2016	ISL80103IRAJZ-T
ISL80103IR18Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL80103IRAJZ-TK
ISL80103IR25Z	6/10/2015	12/10/2015	6/10/2016	ISL80103IRAJZ
ISL80103IR25Z-T	6/10/2015	12/10/2015	6/10/2016	ISL80103IRAJZ-T
ISL80103IR25Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL80103IRAJZ-TK
ISL8010IUZ	6/10/2015	12/10/2015	6/10/2016	ISL80015IRZ-T
ISL8010IUZ-T13	6/10/2015	12/10/2015	6/10/2016	ISL80015IRZ-T
ISL8010IUZ-T7	6/10/2015	12/10/2015	6/10/2016	ISL80015IRZ-T
ISL8013AW	6/10/2015	12/10/2015	6/10/2016	None
ISL8216MIRZ-T7A	6/10/2015	12/10/2015	6/10/2016	ISL8216MIRZ-T
ISL8323IBZ-TS2490	6/10/2015	12/10/2015	6/10/2016	ISL8323IBZ-T
ISL8324IBZ	6/10/2015	12/10/2015	6/10/2016	ISL8323IBZ-T
ISL8324IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL8323IBZ-T
ISL8325IBZ	6/10/2015	12/10/2015	6/10/2016	ISL8323IBZ-T
ISL8325IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL8323IBZ-T
ISL83384ECAZA	6/10/2015	12/10/2015	6/10/2016	ICL3222EIVZ
ISL83384ECAZA-T	6/10/2015	12/10/2015	6/10/2016	ICL3222EIVZ
ISL83385ECAZ	6/10/2015	12/10/2015	6/10/2016	ICL3222EIVZ
ISL83385ECAZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3222EIVZ
ISL83385EIAZ	6/10/2015	12/10/2015	6/10/2016	ICL3222EIVZ
ISL83385EIAZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3222EIVZ
ISL83385EIBZ	6/10/2015	12/10/2015	6/10/2016	ICL3222EIVZ
ISL83385EIBZ-T	6/10/2015	12/10/2015	6/10/2016	ICL3222EIVZ
ISL8394IBZ	6/10/2015	12/10/2015	6/10/2016	ISL8393IBZ-T
ISL8394IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL8393IBZ-T
ISL84052IAZ-TS2687	6/10/2015	12/10/2015	6/10/2016	ISL84052IAZ-T
ISL84053IAZ-TS2687	6/10/2015	12/10/2015	6/10/2016	ISL84052IAZ-T
ISL84523IBZ	6/10/2015	12/10/2015	6/10/2016	ISL84524IUZ-T
ISL84523IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84524IUZ-T
ISL84523IVZ	6/10/2015	12/10/2015	6/10/2016	ISL84524IUZ-T
ISL84523IVZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84524IUZ-T
ISL84541CPZ	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84541IPZ	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84541IUZ	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84541IUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84542CBZ	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84542CBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84542CPZ	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84542IBZ	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84542IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84542IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84542IPZ	6/10/2015	12/10/2015	6/10/2016	ISL84541CBZ-T
ISL84543CBZ	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84543CBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84543CPZ	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84543IBZ	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84543IBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84543IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84543IHZ-TS2568	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84543IPZ	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84544CPZ	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84544IPZ	6/10/2015	12/10/2015	6/10/2016	ISL84544CBZ-T
ISL84716IHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84714IHZ-T
ISL84762IRZ	6/10/2015	12/10/2015	6/10/2016	ISL84714IHZ-T
ISL84762IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84714IHZ-T
ISL84762IUZ	6/10/2015	12/10/2015	6/10/2016	ISL84714IHZ-T
ISL84762IUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84714IHZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL84780IRZ	6/10/2015	12/10/2015	6/10/2016	ISL84781IRZ-T
ISL84780IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84781IRZ-T
ISL84780IVZ	6/10/2015	12/10/2015	6/10/2016	ISL84781IRZ-T
ISL84780IVZ-T	6/10/2015	12/10/2015	6/10/2016	ISL84781IRZ-T
ISL8483EIPZ	6/10/2015	12/10/2015	6/10/2016	ICL3222EIVZ
ISL85402IRZ-TS2753	6/10/2015	12/10/2015	6/10/2016	None
ISL85403IRZ-TS2753	6/10/2015	12/10/2015	6/10/2016	None
ISL8540IVEZ	6/10/2015	12/10/2015	6/10/2016	ISL8560IRZ
ISL8540IVEZ-T	6/10/2015	12/10/2015	6/10/2016	ISL8560IRZ-T
ISL88011IH522Z-T7A	6/10/2015	12/10/2015	6/10/2016	ISL88011IH544Z-T7A
ISL88011IH522Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL88011IH544Z-TK
ISL88012IH522Z-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH522Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH523Z-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH523Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH526Z-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH526Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH529Z-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH529Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH531Z-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH531Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH544Z-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH544Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH546Z-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL88012IH546Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL88013IH523Z-T7A	6/10/2015	12/10/2015	6/10/2016	ISL88013IH526Z-T7A
ISL88013IH523Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL88013IH526Z-TK
ISL88013IH546Z-T7A	6/10/2015	12/10/2015	6/10/2016	ISL88013IH544Z-T7A
ISL88013IH546Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL88013IH544Z-TK
ISL88015IH5Z-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL88015IH5Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL88016IHTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL88016IHTZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL88016IHTZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL8843AUZ	6/10/2015	12/10/2015	6/10/2016	ISL8843AAUZ
ISL8843AUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL8843AAUZ-T
ISL8843MUZ	6/10/2015	12/10/2015	6/10/2016	ISL8843AMUZ
ISL8843MUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL8843AMUZ-T
ISL8850AIRZ-TR5339	6/10/2015	12/10/2015	6/10/2016	None
ISL8850AIRZ-TS2568	6/10/2015	12/10/2015	6/10/2016	None
ISL8850AIRZ-TS2715	6/10/2015	12/10/2015	6/10/2016	None
ISL88694IH5ZTKS2490S	6/10/2015	12/10/2015	6/10/2016	ISL88694IH5Z-TK
ISL88705IP846Z	6/10/2015	12/10/2015	6/10/2016	ISL88705IB846Z
ISL88706IP826Z	6/10/2015	12/10/2015	6/10/2016	ISL88706IB826Z
ISL88706IP829Z	6/10/2015	12/10/2015	6/10/2016	ISL88706IB829Z
ISL88706IP831Z	6/10/2015	12/10/2015	6/10/2016	ISL88706IB831Z
ISL88706IP844Z	6/10/2015	12/10/2015	6/10/2016	ISL88706IB844Z
ISL88707IP846Z	6/10/2015	12/10/2015	6/10/2016	ISL88707IB846Z
ISL88708IP826Z	6/10/2015	12/10/2015	6/10/2016	ISL88708IB826Z
ISL88708IP829Z	6/10/2015	12/10/2015	6/10/2016	ISL88708IB829Z
ISL88708IP831Z	6/10/2015	12/10/2015	6/10/2016	ISL88708IB831Z
ISL88708IP844Z	6/10/2015	12/10/2015	6/10/2016	ISL88708IB844Z
ISL88716IP826Z	6/10/2015	12/10/2015	6/10/2016	ISL88716IB826Z
ISL88731CHRTZ-TR5453	6/10/2015	12/10/2015	6/10/2016	None
ISL88736HRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL88736HRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL88813IP846Z	6/10/2015	12/10/2015	6/10/2016	ISL88813IB846Z

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL89160FBEAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89160FBEAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89160FBEBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89160FBEBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89160FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89160FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89160FRTBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89160FRTBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89161FBEAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89161FBEAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89161FBEBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89161FBEBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89161FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89161FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89161FRTBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89161FRTBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89162FBEAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89162FBEAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89162FBEBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89162FBEBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89162FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89162FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89162FRTBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89162FRTBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89163FBECZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89163FBECZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89163FRTAZ-TR5523	6/10/2015	12/10/2015	6/10/2016	ISL89163FRTAZ-T
ISL89163FRTCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89163FRTCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89164FBECZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89164FBECZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89164FRTCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89164FRTCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89165FBECZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89165FBECZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89165FRTCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89165FRTCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89166FBEAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89166FBEAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89166FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89166FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89167FBEAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89167FBEAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89167FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89167FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89168FBEAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89168FBEAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89168FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89168FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89367FRTAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL89367FRTAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL89410IPZ	6/10/2015	12/10/2015	6/10/2016	ISL89410IBZ
ISL89412IPZ	6/10/2015	12/10/2015	6/10/2016	ISL89412IBZ
ISL9000AIRBBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRBBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRBCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRBCZ-T	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9000AIRBJZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRBJZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRBLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRBLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRGCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRGCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRGPZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRGPZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRJCZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T
ISL9000AIRJCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T
ISL9000AIRJMZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T
ISL9000AIRJMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T
ISL9000AIRJRZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJNZ-T
ISL9000AIRJRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJNZ-T
ISL9000AIRKNZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRKCZ-T
ISL9000AIRKNZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRKCZ-T
ISL9000AIRKPZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRKCZ-T
ISL9000AIRKPZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRKCZ-T
ISL9000AIRLLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRLLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRMMZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRMGZ-T
ISL9000AIRMMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRMGZ-T
ISL9000AIRNCZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRNJZ
ISL9000AIRNCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRNJZ
ISL9000AIRPLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRPLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRPPZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AIRPPZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AMRNCEP	6/10/2015	12/10/2015	6/10/2016	None
ISL9000AMRNCEP-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRBBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRBBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRBCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRBCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRBJZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRBJZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRBLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRBLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRCCZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRCCZ
ISL9000IRCCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRCCZ
ISL9000IRCJZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRCJZ
ISL9000IRCJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRCJZ
ISL9000IRFCZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRFCZ
ISL9000IRFCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRFCZ
ISL9000IRFDZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRFDZ
ISL9000IRFDZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRFDZ
ISL9000IRFJZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRFJZ
ISL9000IRFJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRFJZ
ISL9000IRGCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRGCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRGPZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRGPZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRJBZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ
ISL9000IRJBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ
ISL9000IRJCZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T
ISL9000IRJCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T
ISL9000IRJMZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9000IRJMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T
ISL9000IRJNZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJNZ
ISL9000IRJNZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJNZ
ISL9000IRJRZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T
ISL9000IRJRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRJBZ-T
ISL9000IRK CZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK CZ
ISL9000IRK CZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK CZ
ISL9000IRK FZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK FZ
ISL9000IRK FZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK FZ
ISL9000IRK JZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK JZ
ISL9000IRK JZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK JZ
ISL9000IRK KZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK KZ
ISL9000IRK KZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK KZ
ISL9000IRK NZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK FZ
ISL9000IRK NZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK FZ-T
ISL9000IRK PZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK FZ
ISL9000IRK PZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRK FZ-T
ISL9000IRLLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRLLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9000IRM GZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRM GZ
ISL9000IRM GZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRM GZ-T
ISL9000IRMMZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRM NZ
ISL9000IRMMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRM NZ-T
ISL9000IRM NZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRM NZ
ISL9000IRM NZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRM NZ-T
ISL9000IRN CZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRN FZ
ISL9000IRN CZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRN FZ
ISL9000IRN FZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRN FZ
ISL9000IRN FZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRN FZ
ISL9000IRN JZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRN JZ
ISL9000IRN JZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRN JZ
ISL9000IRN NZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRN NZ
ISL9000IRN NZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRN NZ
ISL9000IRP LZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRC CZ
ISL9000IRP LZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRC CZ
ISL9000IRP PZ	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRC JZ
ISL9000IRP PZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9000AIRC JZ
ISL9001AIR LZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9001AIRN Z-T
ISL9001AIRM Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9001AIRR Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRB Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRB Z-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRC Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRC Z-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRF Z-T	6/10/2015	12/10/2015	6/10/2016	ISL9001AIRF Z-T
ISL9001IRF Z-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRJ Z-T	6/10/2015	12/10/2015	6/10/2016	ISL9001AIRJ Z-T
ISL9001IRJ Z-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRK Z-T	6/10/2015	12/10/2015	6/10/2016	ISL9001AIRK Z-T
ISL9001IRK Z-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRL Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRL Z-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRM Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRM Z-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRN Z-T	6/10/2015	12/10/2015	6/10/2016	ISL9001AIRN Z-T
ISL9001IRN Z-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL9001IRR Z-T	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9001IRRZ-TS2695	6/10/2015	12/10/2015	6/10/2016	None
ISL9003IEBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9003AIEBZ-T
ISL9003IECZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9003AIECZ-T
ISL9003IEFZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9003AIEFZ-T
ISL9003IEHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9003AIEHZ-T
ISL9003IEJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9003AIEJZ-T
ISL9003IEKZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9003AIEKZ-T
ISL9003IEMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9003AIEMZ-T
ISL9003IENZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9003AIENZ-T
ISL9005AIRLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9005AIRMZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9005AIRRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9005IRBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9005AIRBZ-T
ISL9005IRCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9005IRFZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9005IRJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9005AIRJZ-T
ISL9005IRKZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9005AIRKZ-T
ISL9005IRLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9005IRMZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9005IRNZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9005AIRNZ-T
ISL9005IRRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9008IEBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9008AIEBZ-T
ISL9008IECZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9008AIECZ-T
ISL9008IEFZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9008AIEFZ-T
ISL9008IEHZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9008AIEHZ-T
ISL9008IEJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9008AIEJZ-T
ISL9008IEKZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9008AIEKZ-T
ISL9008IEMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9008AIEMZ-T
ISL9008IENZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9008AIENZ-T
ISL9011AIRBBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRBBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRBCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRBCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRBJZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRBJZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRBLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRBLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRGCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRGCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRGPZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRGPZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRJCZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJBZ-T
ISL9011AIRJCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJBZ-T
ISL9011AIRJMZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ-T
ISL9011AIRJMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ-T
ISL9011AIRJRZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ-T
ISL9011AIRJRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ-T
ISL9011AIRKNZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ-T
ISL9011AIRKNZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ-T
ISL9011AIRKPZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ-T
ISL9011AIRKPZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ-T
ISL9011AIRLLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRLLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRMMZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMGZ-T
ISL9011AIRMMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMGZ-T
ISL9011AIRNCZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMNZ-T
ISL9011AIRNCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMNZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9011AIRPLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRPLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRPPZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011AIRPPZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRBBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRBBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRBCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRBCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRBJZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRBJZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRBLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRBLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRCCZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRCCZ
ISL9011IRCCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRCCZ
ISL9011IRCIJZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRCIJZ
ISL9011IRCIJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRCIJZ
ISL9011IRFCZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRFCZ
ISL9011IRFCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRFCZ
ISL9011IRFDZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRFDZ
ISL9011IRFDZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRFDZ
ISL9011IRFJZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRFJZ
ISL9011IRFJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRFJZ
ISL9011IRGCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRGCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRGPZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRGPZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRJBZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJBZ
ISL9011IRJBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJBZ
ISL9011IRJBZ-TS2697	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRJ CZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJBZ
ISL9011IRJ CZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJBZ-T
ISL9011IRJMZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ
ISL9011IRJMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ-T
ISL9011IRJNZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ
ISL9011IRJNZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ
ISL9011IRJRZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ
ISL9011IRJRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRJNZ-T
ISL9011IRKCZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRK CZ
ISL9011IRKCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRK CZ
ISL9011IRKFZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKFZ
ISL9011IRKFZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKFZ
ISL9011IRKJZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKJZ
ISL9011IRKJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKJZ
ISL9011IRKKZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ
ISL9011IRKKZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ
ISL9011IRKNZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ
ISL9011IRKNZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ
ISL9011IRKPZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ
ISL9011IRKPZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRKKZ
ISL9011IRLLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRLLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRMGZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMGZ
ISL9011IRMGZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMGZ
ISL9011IRMMZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMNZ
ISL9011IRMMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMNZ-T
ISL9011IRMNZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMNZ
ISL9011IRMNZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRMNZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9011IRNCZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRNFZ
ISL9011IRNCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRNFZ-T
ISL9011IRNFZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRNFZ
ISL9011IRNFZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRNFZ
ISL9011IRNJZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRNJZ
ISL9011IRNJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRNJZ
ISL9011IRNNZ	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRNNZ
ISL9011IRNNZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9011AIRNNZ
ISL9011IRPLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRPLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRPPZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9011IRPPZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRBJZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRBJZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRFJZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRFJZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRGCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRGCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRJBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRJBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRJ CZ	6/10/2015	12/10/2015	6/10/2016	ISL9012IRJNZ-T
ISL9012IRJ CZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9012IRJNZ-T
ISL9012IRJMZ	6/10/2015	12/10/2015	6/10/2016	ISL9012IRJNZ-T
ISL9012IRJMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9012IRJNZ-T
ISL9012IRJRZ	6/10/2015	12/10/2015	6/10/2016	ISL9012IRJNZ-T
ISL9012IRJRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9012IRJNZ-T
ISL9012IRK CZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRK CZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRKFZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRKFZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRKJZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRKJZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRKKZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRKKZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRLLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRLLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRMMZ	6/10/2015	12/10/2015	6/10/2016	ISL9012IRMNZ-T
ISL9012IRMMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9012IRMNZ-T
ISL9012IRNFZ	6/10/2015	12/10/2015	6/10/2016	ISL9012IRNNZ-T
ISL9012IRNFZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9012IRNNZ-T
ISL9012IRNJZ	6/10/2015	12/10/2015	6/10/2016	ISL9012IRNNZ-T
ISL9012IRNJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9012IRNNZ-T
ISL9012IRPLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9012IRPLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRBBZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRBBZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRBCZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRBCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRBJZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRFJZ-T
ISL9014AIRBJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRFJZ-T
ISL9014AIRBLZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRBLZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRGCZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRFJZ-T
ISL9014AIRGCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRFJZ-T
ISL9014AIRGPZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRGPZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRJCZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRFJZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9014AIRJCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRFJZ-T
ISL9014AIRJMZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRJBZ-T
ISL9014AIRJMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRJBZ-T
ISL9014AIRJRZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRJBZ-T
ISL9014AIRJRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRJBZ-T
ISL9014AIRKNZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRKKZ-T
ISL9014AIRKNZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRKKZ-T
ISL9014AIRKPZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRKKZ-T
ISL9014AIRKPZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRKKZ-T
ISL9014AIRLLZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRK CZ
ISL9014AIRLLZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRK CZ
ISL9014AIRMMZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRMGZ-T
ISL9014AIRMMZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRMGZ-T
ISL9014AIRNCZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRMNZ-T
ISL9014AIRNCZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRMNZ-T
ISL9014AIRPLZ	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRNFZ-T
ISL9014AIRPLZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9014AIRNFZ-T
ISL9014AIRPPZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9014AIRPPZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL90460TIE527Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL90460TIH527Z-TK
ISL90460UIE527Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL90460TIH527Z-TK
ISL90460UIH527Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL90460TIH527Z-TK
ISL90460WIE527Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL90460TIH527Z-TK
ISL90462TIH627Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL90462UIE627Z-TK
ISL90810WAU8Z	6/10/2015	12/10/2015	6/10/2016	ISL90810UAU8Z-TK
ISL90810WAU8Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL90810UAU8Z-TK
ISL90810WIU8Z	6/10/2015	12/10/2015	6/10/2016	ISL90810UAU8Z-TK
ISL90810WIU8Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL90810UAU8Z-TK
ISL9103AIRUNZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9103IRUAZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9103AIRUAZ-T
ISL9103IRUBZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9103AIRUBZ-T
ISL9103IRUCZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9103IRUDZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9103AIRUDZ-T
ISL9103IRUFZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9103AIRUFZ-T
ISL9103IRUJZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9103AIRUJZ-T
ISL9103IRUNZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9103IRUWZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9103AIRUWZ-T
ISL9109IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9110BIRTAZ-TR5453	6/10/2015	12/10/2015	6/10/2016	None
ISL9110IRTAZ-TR5453	6/10/2015	12/10/2015	6/10/2016	None
ISL9113ER7Z-TR5587	6/10/2015	12/10/2015	6/10/2016	None
ISL9200IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9200IRZR5237	6/10/2015	12/10/2015	6/10/2016	None
ISL9200IRZR5239	6/10/2015	12/10/2015	6/10/2016	None
ISL9200IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9200IRZ-TR5237	6/10/2015	12/10/2015	6/10/2016	None
ISL9200IRZ-TR5239	6/10/2015	12/10/2015	6/10/2016	None
ISL9201IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9201IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9203CRZR5220	6/10/2015	12/10/2015	6/10/2016	None
ISL9203CRZ-TR5220	6/10/2015	12/10/2015	6/10/2016	None
ISL9206ADHZR5335-060	6/10/2015	12/10/2015	6/10/2016	None
ISL9206ADRTZR5335-60	6/10/2015	12/10/2015	6/10/2016	None
ISL9206DHZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9206DHZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9206DRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9211AIRU48XZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9211BIRU58XZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL9211AIRU58XZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9211BIRU58XZ-T
ISL9211AIRU68XZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9211BIRU58XZ-T
ISL9211IRU58XZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9211BIRU58XZ-T
ISL9211IRU68XZ-T	6/10/2015	12/10/2015	6/10/2016	ISL9211BIRU58XZ-T
ISL9212IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9212IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9221IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9221IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9222AIRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9305IRH4CFCZR5613	6/10/2015	12/10/2015	6/10/2016	None
ISL94200IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL94201IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9491AERZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9491AERZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9502CRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9502CRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL9505AHRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL9505AHRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL95310WIU10Z	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95310WIU10Z-TK	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95311UIU10Z	6/10/2015	12/10/2015	6/10/2016	None
ISL95311UIU10Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL95710UIU10Z	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95710UIU10Z-T	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95710WIU10Z	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95710WIU10Z-T	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95711UIU10Z	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95711UIU10Z-T	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95711WIU10Z	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95711WIU10Z-T	6/10/2015	12/10/2015	6/10/2016	ISL95310UIU10Z-TK
ISL95810UIU8Z-TR5391	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811UFRTZ	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811UFRTZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811UFUZ	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811UFUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811UFUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811WFRTZ	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811WFRTZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811WFUZ	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811WFUZ-T	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95811WFUZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL95810UIU8Z-T
ISL95831AHRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL95831AHRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL95838HRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL95838IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL95839HRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL95839HRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL95874HRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL95874IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL95875HRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL95875IRUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL96017UIRT8Z	6/10/2015	12/10/2015	6/10/2016	None
ISL96017UIRT8Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL96017UIRT8Z-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL96017WIRT8Z	6/10/2015	12/10/2015	6/10/2016	None
ISL96017WIRT8Z-T	6/10/2015	12/10/2015	6/10/2016	None
ISL96017WIRT8Z-TK	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL97642IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97642IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97648IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97648IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97648IRTZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL97649AIRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97649AIRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97649BIRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97649BIRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97670IRZR5497	6/10/2015	12/10/2015	6/10/2016	None
ISL97670IRZR5595	6/10/2015	12/10/2015	6/10/2016	None
ISL97670IRZR5596	6/10/2015	12/10/2015	6/10/2016	None
ISL97670IRZ-TR5595	6/10/2015	12/10/2015	6/10/2016	None
ISL97670IRZ-TR5497	6/10/2015	12/10/2015	6/10/2016	None
ISL97670IRZ-TR5595	6/10/2015	12/10/2015	6/10/2016	None
ISL97670IRZ-TR5596	6/10/2015	12/10/2015	6/10/2016	None
ISL97671AIRZ-TR5533	6/10/2015	12/10/2015	6/10/2016	None
ISL97671IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97671IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97671IRZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL97672IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97672IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97672IRZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL97674IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97674IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97674IRZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL97675IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97675IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97675IRZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL97676IRZ	6/10/2015	12/10/2015	6/10/2016	ISL97671AIRZ
ISL97676IRZ-T	6/10/2015	12/10/2015	6/10/2016	ISL97671AIRZ
ISL97676IRZ-TK	6/10/2015	12/10/2015	6/10/2016	ISL97671AIRZ
ISL97677IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97677IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97677IRZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL97680IRZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97680IRZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97680IRZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL97685IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL97685IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL97801ARZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL98012IUZ	6/10/2015	12/10/2015	6/10/2016	None
ISL98012IUZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL98012IUZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL98602IRAAZR5453	6/10/2015	12/10/2015	6/10/2016	None
ISL98602IRAAZ-TR5453	6/10/2015	12/10/2015	6/10/2016	None
ISL98603IRAAZ	6/10/2015	12/10/2015	6/10/2016	None
ISL98603IRAAZ-T	6/10/2015	12/10/2015	6/10/2016	None
ISL98603IRAAZ-T7A	6/10/2015	12/10/2015	6/10/2016	None
ISL98603IRAAZ-TK	6/10/2015	12/10/2015	6/10/2016	None
ISL98604IRTZ	6/10/2015	12/10/2015	6/10/2016	None
ISL98604IRTZ-T	6/10/2015	12/10/2015	6/10/2016	None
KAD2708C-10Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2708C-17Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2708C-21Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2708C-27Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2708L-10Q68	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
KAD2708L-17Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2708L-21Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2708L-27Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2708L-35Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2710C-10Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2710C-17Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2710C-21Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2710C-27Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2710L-10Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2710L-17Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2710L-21Q68	6/10/2015	12/10/2015	6/10/2016	None
KAD2710L-27Q68	6/10/2015	12/10/2015	6/10/2016	None
QHX100IQSR	6/10/2015	12/10/2015	6/10/2016	None
QHX100IQT7	6/10/2015	12/10/2015	6/10/2016	None
QHX220IQSR	6/10/2015	12/10/2015	6/10/2016	None
QHX220IQT7	6/10/2015	12/10/2015	6/10/2016	None
TW2388-LA2-GR	6/10/2015	12/10/2015	6/10/2016	TW8832S-LB1-CR
TW2840-BA1-FR	6/10/2015	12/10/2015	6/10/2016	None
TW2960-LA1-CR	6/10/2015	12/10/2015	6/10/2016	TW2964-LA2-CR, TW2964-LA2-CR128, TW2984-NA2-CR
TW5866-BA2-CR	6/10/2015	12/10/2015	6/10/2016	TW2819-BA2-CR, TW2809-BC1-GR
TW6805A-LA2-GR	6/10/2015	12/10/2015	6/10/2016	TW6865-TA1-CR, TW6869-TA1-CR
TW8806-PB2-GRR5437	6/10/2015	12/10/2015	6/10/2016	TW8806EP-PB2-GRS
TW8806-PB2-GRS	6/10/2015	12/10/2015	6/10/2016	TW8806EP-PB2-GRS
TW8816AT-LA3-GRSH	6/10/2015	6/10/2016	#####	TW8816AT-LB3-GRSH
TW8816AT-LA3-GRSHT	6/10/2015	6/10/2016	#####	TW8816AT-LB3-GRSHT
TW8816EP-LA3-GRSV	6/10/2015	12/10/2015	6/10/2016	TW8816-LB3-GRS
TW8816-LB2-GRS	6/10/2015	12/10/2015	6/10/2016	TW8816-LB3-GRS
TW8817AT-TA3-GRSH	6/10/2015	6/10/2016	#####	None
TW8817-TA5-GRS	6/10/2015	12/10/2015	6/10/2016	TW8817-TA3-GRS; TW8817-TA6-GRSHT
TW8817-TA5-GRSH	6/10/2015	12/10/2015	6/10/2016	TW8817-TA3-GRST; TW8817-TA6-GRSHT
TW8817-TA5-GRSHT	6/10/2015	12/10/2015	6/10/2016	TW8817-TA3-GRS; TW8817-TA6-GRSHT
TW9906-TA3-GR	6/10/2015	12/10/2015	6/10/2016	TW9906-TB2-GR, TW9912-NA3-CR
X28HC256J-12	6/10/2015	12/10/2015	6/10/2016	X28HC256JZ-12
X28HC256J-12T1	6/10/2015	12/10/2015	6/10/2016	X28HC256JZ-12T1
X28HC256J-15	6/10/2015	12/10/2015	6/10/2016	X28HC256JZ-15
X28HC256J-15T1	6/10/2015	12/10/2015	6/10/2016	X28HC256JZ-15T1
X28HC256JI-12T1	6/10/2015	12/10/2015	6/10/2016	X28HC256JIZ-12T1
X28HC256JI-15T1	6/10/2015	12/10/2015	6/10/2016	X28HC256JIZ-15T1
X28HC256JI-15T2	6/10/2015	12/10/2015	6/10/2016	X28HC256JIZ-15T1
X28HC256JI-90C7992	6/10/2015	12/10/2015	6/10/2016	X28HC256JI-90, X28HC256JIZ-90
X28HC256JI-90T1C7992	6/10/2015	12/10/2015	6/10/2016	X28HC256JI-90T1, X28HC256JIZ-90T1
X28HC256S-12	6/10/2015	12/10/2015	6/10/2016	X28HC256SZ-12
X28HC256S-90	6/10/2015	12/10/2015	6/10/2016	X28HC256SI-90, X28HC256SIZ-90
X28HC256SI-15	6/10/2015	12/10/2015	6/10/2016	X28HC256SIZ-12
X28HC256SI-15T1	6/10/2015	12/10/2015	6/10/2016	X28HC256SIZ-12
X28HC256SIZ-15	6/10/2015	12/10/2015	6/10/2016	X28HC256SIZ-12
X28HC64J-12	6/10/2015	12/10/2015	6/10/2016	X28HC64JZ-12
X28HC64J-12T1	6/10/2015	12/10/2015	6/10/2016	X28HC64JZ-12T1
X28HC64J-70	6/10/2015	12/10/2015	6/10/2016	X28HC64JZ-70
X28HC64J-70T1	6/10/2015	12/10/2015	6/10/2016	X28HC64JZ-70T1
X28HC64J-90	6/10/2015	12/10/2015	6/10/2016	X28HC64JIZ-90
X28HC64J-90T1	6/10/2015	12/10/2015	6/10/2016	X28HC64JIZ-90T1
X28HC64JI-12	6/10/2015	12/10/2015	6/10/2016	X28HC64JIZ-12
X28HC64JI-12T1	6/10/2015	12/10/2015	6/10/2016	X28HC64JIZ-12T1
X28HC64JI-70	6/10/2015	12/10/2015	6/10/2016	X28HC64JIZ-70
X28HC64JI-70T1	6/10/2015	12/10/2015	6/10/2016	X28HC64JIZ-70T1
X28HC64JI-90	6/10/2015	12/10/2015	6/10/2016	X28HC64JIZ-90

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X28HC64JI-90T1	6/10/2015	12/10/2015	6/10/2016	X28HC64JIZ-90T1
X28HC64JI-90T2	6/10/2015	12/10/2015	6/10/2016	X28HC64JIZ-90T1
X28HT010W	6/10/2015	12/10/2015	6/10/2016	None
X40020S14IZ-A	6/10/2015	12/10/2015	6/10/2016	None
X40020S14IZ-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40020S14IZ-B	6/10/2015	12/10/2015	6/10/2016	None
X40020S14IZ-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40020S14Z-A	6/10/2015	12/10/2015	6/10/2016	None
X40020S14Z-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40020S14Z-B	6/10/2015	12/10/2015	6/10/2016	None
X40020S14Z-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40021S14IZ-A	6/10/2015	12/10/2015	6/10/2016	None
X40021S14IZ-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40021S14IZ-B	6/10/2015	12/10/2015	6/10/2016	None
X40021S14IZ-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40021S14Z-A	6/10/2015	12/10/2015	6/10/2016	None
X40021S14Z-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40021S14Z-B	6/10/2015	12/10/2015	6/10/2016	None
X40021S14Z-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40030S14IZ-A	6/10/2015	12/10/2015	6/10/2016	None
X40030S14IZ-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40030S14IZ-B	6/10/2015	12/10/2015	6/10/2016	None
X40030S14IZ-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40030S14Z-A	6/10/2015	12/10/2015	6/10/2016	None
X40030S14Z-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40030S14Z-B	6/10/2015	12/10/2015	6/10/2016	None
X40030S14Z-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40031S14IZ-A	6/10/2015	12/10/2015	6/10/2016	None
X40031S14IZ-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40031S14IZ-B	6/10/2015	12/10/2015	6/10/2016	None
X40031S14IZ-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40031S14Z-A	6/10/2015	12/10/2015	6/10/2016	None
X40031S14Z-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40031S14Z-B	6/10/2015	12/10/2015	6/10/2016	None
X40031S14Z-BT1	6/10/2015	12/10/2015	6/10/2016	None
X4003M8IZ	6/10/2015	12/10/2015	6/10/2016	None
X4003M8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X4003M8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X4003M8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X4003M8Z	6/10/2015	12/10/2015	6/10/2016	None
X4003M8Z-2.7	6/10/2015	12/10/2015	6/10/2016	None
X4003M8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X4003M8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X4003S8IZ	6/10/2015	12/10/2015	6/10/2016	None
X4003S8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X4003S8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X4003S8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X4003S8Z	6/10/2015	12/10/2015	6/10/2016	None
X4003S8Z-2.7	6/10/2015	12/10/2015	6/10/2016	None
X4003S8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X4003S8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X4005M8IZ	6/10/2015	12/10/2015	6/10/2016	None
X4005M8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X4005M8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X4005M8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X4005M8Z	6/10/2015	12/10/2015	6/10/2016	None
X4005M8Z-2.7	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X4005M8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X4005M8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X4005S8IZ	6/10/2015	12/10/2015	6/10/2016	None
X4005S8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X4005S8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X4005S8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X4005S8Z	6/10/2015	12/10/2015	6/10/2016	None
X4005S8Z-2.7	6/10/2015	12/10/2015	6/10/2016	None
X4005S8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X4005S8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X40415V8IZ-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40420S14IZ-A	6/10/2015	12/10/2015	6/10/2016	None
X40420S14IZ-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40420S14IZ-B	6/10/2015	12/10/2015	6/10/2016	None
X40420S14IZ-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40420S14Z-A	6/10/2015	12/10/2015	6/10/2016	None
X40420S14Z-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40420S14Z-B	6/10/2015	12/10/2015	6/10/2016	None
X40420S14Z-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40421S14IZ-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40421S14IZ-B	6/10/2015	12/10/2015	6/10/2016	None
X40421S14IZ-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40421S14Z-A	6/10/2015	12/10/2015	6/10/2016	None
X40421S14Z-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40421S14Z-B	6/10/2015	12/10/2015	6/10/2016	None
X40421S14Z-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40430S14IZ-A	6/10/2015	12/10/2015	6/10/2016	None
X40430S14IZ-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40430S14IZ-B	6/10/2015	12/10/2015	6/10/2016	None
X40430S14IZ-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40430S14Z-A	6/10/2015	12/10/2015	6/10/2016	None
X40430S14Z-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40430S14Z-B	6/10/2015	12/10/2015	6/10/2016	None
X40430S14Z-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40431S14IZ-A	6/10/2015	12/10/2015	6/10/2016	None
X40431S14IZ-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40431S14IZ-B	6/10/2015	12/10/2015	6/10/2016	None
X40431S14IZ-BT1	6/10/2015	12/10/2015	6/10/2016	None
X40431S14Z-A	6/10/2015	12/10/2015	6/10/2016	None
X40431S14Z-AT1	6/10/2015	12/10/2015	6/10/2016	None
X40431S14Z-B	6/10/2015	12/10/2015	6/10/2016	None
X40431S14Z-BT1	6/10/2015	12/10/2015	6/10/2016	None
X4043PIZ	6/10/2015	12/10/2015	6/10/2016	X4043M8IZ
X4043PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	X4043M8IZ-2.7
X4043PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X4043M8IZ-2.7A
X4043PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X4043M8IZ-4.5A
X4043PZ	6/10/2015	12/10/2015	6/10/2016	X4043M8Z
X4043PZ-2.7	6/10/2015	12/10/2015	6/10/2016	X4043M8Z-2.7
X4043PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X4043M8Z-2.7A
X4043PZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X4043M8Z-4.5A
X4045M8IZ	6/10/2015	12/10/2015	6/10/2016	X4045S8IZ
X4045M8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	X4045S8IZ-2.7
X4045M8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X4045S8IZ-2.7A
X4045M8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X4045S8IZ-4.5A
X4045M8Z	6/10/2015	12/10/2015	6/10/2016	X4045S8Z
X4045M8Z-2.7	6/10/2015	12/10/2015	6/10/2016	X4045S8Z-2.7
X4045M8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	X4045S8Z-2.7A

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X4045M8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	X4045S8Z-4.5A
X4045PIZ	6/10/2015	12/10/2015	6/10/2016	X4045S8IZ
X4045PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	X4045S8IZ-2.7
X4045PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X4045S8IZ-2.7A
X4045PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X4045S8IZ-4.5A
X4045PZ	6/10/2015	12/10/2015	6/10/2016	X4045S8Z
X4045PZ-2.7	6/10/2015	12/10/2015	6/10/2016	X4045S8Z-2.7
X4045PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X4045S8Z-2.7A
X4045PZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X4045S8Z-4.5A
X5001PIZ	6/10/2015	12/10/2015	6/10/2016	None
X5001PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5001PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5001PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5001PZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5001PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5001S8IZ	6/10/2015	12/10/2015	6/10/2016	None
X5001S8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5001S8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5001S8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5001S8Z	6/10/2015	12/10/2015	6/10/2016	None
X5001S8Z-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5001S8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5001S8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5043V14IZ	6/10/2015	12/10/2015	6/10/2016	X5043M8IZ
X5045M8IZ	6/10/2015	12/10/2015	6/10/2016	X5045S8IZ-2.7
X5045M8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	X5045S8IZ-2.7
X5045M8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X5045S8IZ-2.7A
X5045M8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X5045S8IZ-4.5A
X5045M8Z	6/10/2015	12/10/2015	6/10/2016	X5045S8Z
X5045M8Z-2.7	6/10/2015	12/10/2015	6/10/2016	X5045S8Z-2.7
X5045M8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	X5045S8Z-2.7A
X5045M8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	X5045S8Z-4.5A
X5045W-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5083PIZ	6/10/2015	12/10/2015	6/10/2016	None
X5083PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5083PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5083PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5083PZ	6/10/2015	12/10/2015	6/10/2016	None
X5083PZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5083PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5083PZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5083V8IZ	6/10/2015	12/10/2015	6/10/2016	X5083S8IZ
X5083V8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	X5083S8IZ-2.7
X5163PIZ	6/10/2015	12/10/2015	6/10/2016	X5163S8IZ
X5163PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	X5163S8IZ-2.7
X5163PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X5163S8IZ-2.7A
X5163PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X5163S8IZ-4.5A
X5163PZ	6/10/2015	12/10/2015	6/10/2016	X5163S8Z
X5163PZ-2.7	6/10/2015	12/10/2015	6/10/2016	X5163S8Z-2.7
X5163PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X5163S8Z-2.7A
X5163PZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X5163S8Z-4.5A
X5165PIZ	6/10/2015	12/10/2015	6/10/2016	None
X5165PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5165PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5165PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5165PZ	6/10/2015	12/10/2015	6/10/2016	None
X5165PZ-2.7	6/10/2015	12/10/2015	6/10/2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X5165PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5165PZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5165S8IZ	6/10/2015	12/10/2015	6/10/2016	None
X5165S8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5165S8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5165S8IZ-2.7T1	6/10/2015	12/10/2015	6/10/2016	None
X5165S8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5165S8IZT1	6/10/2015	12/10/2015	6/10/2016	None
X5165S8Z	6/10/2015	12/10/2015	6/10/2016	None
X5165S8Z-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5165S8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5165S8Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	None
X5165S8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5165S8ZT1	6/10/2015	12/10/2015	6/10/2016	None
X5168PIZ	6/10/2015	12/10/2015	6/10/2016	None
X5168PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5168PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5168PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5168PZ	6/10/2015	12/10/2015	6/10/2016	None
X5168PZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5168PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5168PZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5168S8IZ	6/10/2015	12/10/2015	6/10/2016	None
X5168S8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5168S8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5168S8IZ-2.7T1	6/10/2015	12/10/2015	6/10/2016	None
X5168S8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5168S8IZ-4.5AT1	6/10/2015	12/10/2015	6/10/2016	None
X5168S8IZT1	6/10/2015	12/10/2015	6/10/2016	None
X5168S8Z	6/10/2015	12/10/2015	6/10/2016	None
X5168S8Z-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5168S8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5168S8Z-2.7AT1	6/10/2015	12/10/2015	6/10/2016	None
X5168S8Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	None
X5168S8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5168S8ZT1	6/10/2015	12/10/2015	6/10/2016	None
X5169PIZ	6/10/2015	12/10/2015	6/10/2016	None
X5169PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5169PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5169PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5169PZ	6/10/2015	12/10/2015	6/10/2016	None
X5169PZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5169PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5169PZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5169S8IZ	6/10/2015	12/10/2015	6/10/2016	None
X5169S8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5169S8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5169S8IZ-2.7T1	6/10/2015	12/10/2015	6/10/2016	None
X5169S8IZ-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5169S8IZT1	6/10/2015	12/10/2015	6/10/2016	None
X5169S8Z	6/10/2015	12/10/2015	6/10/2016	None
X5169S8Z-2.7	6/10/2015	12/10/2015	6/10/2016	None
X5169S8Z-2.7A	6/10/2015	12/10/2015	6/10/2016	None
X5169S8Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	None
X5169S8Z-4.5A	6/10/2015	12/10/2015	6/10/2016	None
X5169S8ZT1	6/10/2015	12/10/2015	6/10/2016	None
X5323PIZ	6/10/2015	12/10/2015	6/10/2016	X5323S8IZ

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X5323PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	X5323S8IZ-2.7
X5323PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X5323S8IZ-2.7A
X5323PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X5323S8IZ-4.5A
X5323PZ	6/10/2015	12/10/2015	6/10/2016	X5323S8Z
X5323PZ-2.7	6/10/2015	12/10/2015	6/10/2016	X5323S8Z-2.7
X5323PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X5323S8Z-2.7A
X5323PZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X5323S8Z-4.5A
X5328PIZ	6/10/2015	12/10/2015	6/10/2016	X5328S8IZ
X5328PIZ-2.7	6/10/2015	12/10/2015	6/10/2016	X5328S8IZ-2.7
X5328PIZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X5328S8IZ-2.7A
X5328PIZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X5328S8IZ-4.5A
X5328PZ	6/10/2015	12/10/2015	6/10/2016	X5328S8Z
X5328PZ-2.7	6/10/2015	12/10/2015	6/10/2016	X5328S8Z-2.7
X5328PZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X5328S8Z-2.7A
X5328PZ-4.5A	6/10/2015	12/10/2015	6/10/2016	X5328S8Z-4.5A
X5329S8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	X5329S8Z-2.7
X5329S8IZ-2.7A	6/10/2015	12/10/2015	6/10/2016	X5329S8Z-2.7A
X60003DIG3Z-41	6/10/2015	12/10/2015	6/10/2016	X60003BIG3Z-41T1
X60003DIG3Z-41T1	6/10/2015	12/10/2015	6/10/2016	X60003BIG3Z-41T1
X9015UW	6/10/2015	12/10/2015	6/10/2016	None
X9015WS8Z	6/10/2015	12/10/2015	6/10/2016	X9015US8Z
X9015WS8Z-2.7	6/10/2015	12/10/2015	6/10/2016	X9015US8Z-2.7
X9015WS8Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	X9015US8Z-2.7T1
X9015WS8ZT1	6/10/2015	12/10/2015	6/10/2016	X9015US8ZT1
X9221AWPIZ	6/10/2015	12/10/2015	6/10/2016	X9221AWSZT1
X9221AWPZ	6/10/2015	12/10/2015	6/10/2016	X9221AWSZT1
X9241AMPIZ	6/10/2015	12/10/2015	6/10/2016	X9241AMSZT1
X9241AMPZ	6/10/2015	12/10/2015	6/10/2016	X9241AMSZT1
X9241AUVZ	6/10/2015	12/10/2015	6/10/2016	X9241AMSZT1
X9241AUVZT1	6/10/2015	12/10/2015	6/10/2016	X9241AUSZT1
X9241AWW	6/10/2015	12/10/2015	6/10/2016	None
X9241AYPIZ	6/10/2015	12/10/2015	6/10/2016	X9241AYSIZ
X9241AYPZ	6/10/2015	12/10/2015	6/10/2016	X9241AYSIZ
X9241AYVZ	6/10/2015	12/10/2015	6/10/2016	X9241AYSIZ
X9241AYVZT1	6/10/2015	12/10/2015	6/10/2016	X9241AYVIZT1
X9241AYW	6/10/2015	12/10/2015	6/10/2016	None
X9271UV14Z-2.7	6/10/2015	12/10/2015	6/10/2016	X9271UV14IZ-2.7T1
X9271UV14Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	X9271UV14IZ-2.7T1
X9271UV14ZT1	6/10/2015	12/10/2015	6/10/2016	X9271UV14IZ-2.7T1
X9313UPZ	6/10/2015	12/10/2015	6/10/2016	X9313UMIZT1
X9313WPZ-3	6/10/2015	12/10/2015	6/10/2016	X9313UMIZ-3T1
X9313ZPIZ	6/10/2015	12/10/2015	6/10/2016	X9313ZSIZT1
X9313ZPZ-3	6/10/2015	12/10/2015	6/10/2016	X9313ZSIZ-3T1
X93154UM8IZ-3	6/10/2015	12/10/2015	6/10/2016	None
X93154UM8IZ-3T1	6/10/2015	12/10/2015	6/10/2016	None
X93155UM8IZ	6/10/2015	12/10/2015	6/10/2016	None
X93155UM8IZT1	6/10/2015	12/10/2015	6/10/2016	None
X93156UM8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X93156UM8IZ-2.7T1	6/10/2015	12/10/2015	6/10/2016	None
X93156WM8IZ	6/10/2015	12/10/2015	6/10/2016	None
X93156WM8IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X93156WM8IZ-2.7T1	6/10/2015	12/10/2015	6/10/2016	None
X9317WW	6/10/2015	12/10/2015	6/10/2016	None
X9319WW	6/10/2015	12/10/2015	6/10/2016	None
X9400WS24IZ2.7TS2705	6/10/2015	3/10/2016	3/10/2017	X9400WS24IZT1
X9400WS24IZ27T1S2705	6/10/2015	3/10/2016	3/10/2017	X9400WS24IZT1
X9400WS24ZT1	6/10/2015	12/10/2015	6/10/2016	X9400WS24IZT1

Exact Intersil Part # No other variation is being impacted.	Notice PLC15033 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X9400WV24IZ-2.7	6/10/2015	12/10/2015	6/10/2016	X9400WS24IZT1
X9400WV24IZ-2.7T1	6/10/2015	12/10/2015	6/10/2016	X9400WS24IZT1
X9400WV24Z	6/10/2015	12/10/2015	6/10/2016	X9400WS24IZT1
X9400WV24Z-2.7	6/10/2015	12/10/2015	6/10/2016	X9400WS24IZT1
X9400WV24Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	X9400WS24IZT1
X9400WV24ZT1	6/10/2015	12/10/2015	6/10/2016	X9400WS24IZT1
X9401WS24IZ	6/10/2015	12/10/2015	6/10/2016	X9401WS24IZ-2.7T1
X9401WS24IZT1	6/10/2015	12/10/2015	6/10/2016	X9401WS24IZ-2.7T1
X9401WS24Z	6/10/2015	12/10/2015	6/10/2016	X9401WS24IZ-2.7T1
X9401WS24Z-2.7	6/10/2015	12/10/2015	6/10/2016	X9401WS24IZ-2.7T1
X9401WS24Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	X9401WS24IZ-2.7T1
X9401WS24ZT1	6/10/2015	12/10/2015	6/10/2016	X9401WS24IZ-2.7T1
X9401WV24IZ	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9401WV24IZT1	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9401WV24Z	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9401WV24Z-2.7	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9401WV24Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9401WV24ZT1	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9409WV24IZ	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9409WV24IZT1	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9409WV24Z	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9409WV24Z-2.7	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9409WV24Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9409WV24ZT1	6/10/2015	12/10/2015	6/10/2016	X9401WV24IZ-2.7T1
X9418YS24IZ	6/10/2015	12/10/2015	6/10/2016	None
X9418YS24IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X9418YS24Z	6/10/2015	12/10/2015	6/10/2016	None
X9418YS24Z-2.7	6/10/2015	12/10/2015	6/10/2016	None
X9418YV24IZ	6/10/2015	12/10/2015	6/10/2016	None
X9418YV24IZ-2.7	6/10/2015	12/10/2015	6/10/2016	None
X9418YV24IZ-2.7T1	6/10/2015	12/10/2015	6/10/2016	None
X9418YV24IZ-2.7T2	6/10/2015	12/10/2015	6/10/2016	None
X9418YV24Z	6/10/2015	12/10/2015	6/10/2016	None
X9418YV24Z-2.7	6/10/2015	12/10/2015	6/10/2016	None
X9429WS16IZ-2.7	6/10/2015	12/10/2015	6/10/2016	X9429WS16IZT1
X9429WS16IZ-2.7T1	6/10/2015	12/10/2015	6/10/2016	X9429WS16IZT1
X9429WS16Z	6/10/2015	12/10/2015	6/10/2016	X9429WS16IZT1
X9429WS16Z-2.7	6/10/2015	12/10/2015	6/10/2016	X9429WS16IZT1
X9429WS16Z-2.7T1	6/10/2015	12/10/2015	6/10/2016	X9429WS16IZT1
X9429WS16ZT1	6/10/2015	12/10/2015	6/10/2016	X9429WS16IZT1
X9C102W	6/10/2015	12/10/2015	6/10/2016	None
X9C103W	6/10/2015	12/10/2015	6/10/2016	None
ZL2103ALAF	6/10/2015	12/10/2015	6/10/2016	ZL2102ALAFK
ZL2103ALAFK	6/10/2015	12/10/2015	6/10/2016	ZL2102ALAFK
ZL2103ALAFK	6/10/2015	12/10/2015	6/10/2016	ZL2102ALAFK