

## Product Advisory


**Issue Date: February 17, 2020**

**Reason:**

This is an advisory on original EOL-BCA-01431; Issue date: April 29, 2019.

This is a notification with regard to EOL-BCA-01431, as it relates to RoHS EU directive 2011/65/EU in 2011 and its amendment Directive (EU) 2015/863 of 31 March 2015 that material shipped after March 1<sup>st</sup> 2020 will continue to have Eutectic bump interconnect metallurgy.

Below is the label information:



How to read the label?

- RoHS Exempt, Non-RoHS Compliant – these are exempt under exemption 15 for shipments per current EU RoHS directive prior to March 1<sup>st</sup> 2020

**Parts Affected:**

- BCM6812IFSBG
- BCM6812KFEBG
- BCM6812RKFEGB
- BCM68181KFSBG
- BCM6818GKFBSG
- BCM6818KFSB
- BCM6818KFSBG
- BCM6818SRKFEGB