

PCN Number:	20180905002	PCN Date:	September 06, 2018
Title:	Datasheet for DRV5013-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



DRV5013-Q1

SLIS162H-DECEMBER 2014-REVISED AUGUST 2018

Changes from Revision G (October 2017) to Revision H

Page

- *Changed Power Supply Recommendations section* 19

The datasheet number will be changing.

Device Family	Change From:	Change To:
DRV5013-Q1	SLIS162G	SLIS162H

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/DRV5013-Q1>

Reason for Change:

Added supplemental information to clarify power supply recommendations

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

DRV5013ADEDDBZRQ1	DRV5013ADQLPGQ1	DRV5013AGQLPGMQ1	DRV5013BCQDBZTQ1
DRV5013ADEDDBZTQ1	DRV5013AGEDBZRQ1	DRV5013AGQLPGQ1	DRV5013BCQLPGMQ1
DRV5013ADELPGMQ1	DRV5013AGEDBZTQ1	DRV5013BCEDBZRQ1	DRV5013BCQLPGQ1
DRV5013ADELPGQ1	DRV5013AGELPGMQ1	DRV5013BCEDBZTQ1	DRV5013FAEDBZRQ1
DRV5013ADQDBZRQ1	DRV5013AGELPGQ1	DRV5013BCELPGMQ1	
DRV5013ADQDBZTQ1	DRV5013AGQDBZRQ1	DRV5013BCELPGQ1	
DRV5013ADQLPGMQ1	DRV5013AGQDBZTQ1	DRV5013BCQDBZRQ1	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com