



Date: March 31, 2021

PCN No#: 033121-1

PCN Title: Products End of Life Notification

Dear Customer:

This is an announcement of End of Life products that are currently being offered by Micro Commercial Components Corp(MCC) .We request that you acknowledge receipt of this notification within 30 days of the date of this PCN. Please refer to the implementation date of this change as it is stated in the attached PCN form. Please contact your local sales representative to acknowledge receipt of this PCN.

If you have any questions about PCN's products, please contact your local sales representative.

Sincerely,

MCC PCN Team



Products End of Life Notification

Notification Date	Implementation Date	Last Time Buy Ship Date	Change Type	PCN No
March 31, 2021	September 30,2021	September 30,2021	Products End of Life (EOL)	033121-1
TITLE				
Products End of Life Notification				
DESCRIPTION OF CHANGE				
MCC has undergone a review of its core business and products , and determined to discontinue below product.This PCN is being issued to notify customers that products listed below will no longer be available from MCC. For select products on this PCN, replacement parts are being offered and are available for immediate substitution. Please contact your local representatives for any questions or additional information.				
IMPACT				
Table 1: EOL Devices With Possible Replacement Parts. Table 2: EOL Devices Without Possible Replacement Parts.				
PRODUCTS AFFECTED				
See Table 1~2 .				
WEB LINKS				
Terms And Conditions:	https://www.mccsemi.com/Home/TermsAndConditions			
For More Information Contact:	https://www.mccsemi.com/Contact/Index			
Products:	https://www.mccsemi.com/ProductCategories			
DISCLAIMER				
Unless a MCC Sales representative is contacted in writing within 30 days of the posting of this notice, all changes described in this announcement are considered approved.				

Table 1 - EOL Devices With Possible Replacement Parts

EOL Parts	Possible Replacements	EOL Parts	Possible Replacements	EOL Parts	Possible Replacements
1N4148WL-TP	1N4148W-TP	MCQ4407-TP	MCQ4407B-TP	MCU50N06-TP	MCU90N06A-TP
2N7002KDWA-TP	2N7002KDW-TP	MCQ4410-TP	MCQ16N03-TP	MCU60N04-TP	MCU60N04A-TP
ESD0561P1-TP	ESD0571P6-TP	MCQ4503-TP	MCQ4503B-TP	MCX3152P-TP	SIX3139K-TP
ESDLC0544P5-TP	ESDLC0534DFN10-TP	MCQ4828-TP	MCQD05N06-TP	SBLB1040-TP	MBRB1040-TP
ESDLC5V0LTB-TP	ESDSBL5V0LTB-TP	MCQ6005-TP	MCQD05N06-TP	SIL2623-TP	SIL2623A-TP
ESDLC0524DFN10-TP	ESDLC0524DFN10-TP	MCU10N10-TP	MCU15N10A-TP	SIL3724-TP	SIL3724A-TP
ESDU5V0H4-TP	SRV05-4C-TP	MCU15N10-TP	MCU15N10A-TP	SRV05-4-TP	SRV05-4C-TP
MCQ4406-TP	MCQ4406A-TP	MCU18N10-TP	MCU20N10-TP	TL431BU-TP	TL431KA-TP
MCQ4407A-TP	MCQ4407B-TP	TL431V-TP	TL431KA-TP	TL431K-TP	TL431KA-TP

Table 2 - EOL Devices Without Possible Replacement Parts

B0520WTL-TP	ESDLC2504P9-TP	ESDLC5V0M5-TP	MBRLP20100-TP	MCQ60P05-TP	SIC1060A-TP
ESD12VK4-TP	ESDLC3304P5-TP	ESDLC5V0PB8-TP	MCD02N60-TP	MCS2010-TP	SL12-TP
ESD5V0L4-TP	ESDLC3324P5-TP	ESDLC5V0T5-TP	MCDS04N60-TP	MCS8804-TP	SM05BT-TP
ESD5V0M5-TP	ESDLC3374P9-TP	ESDN12VD3-TP	MCP04N80-BP	MCS8820-TP	TL431X-TP
ESDH3V0D5B-TP	ESDLC3V0L4-TP	ESDU5V0C2-TP	MCP140N10Y-BP	MCU02N80-TP	UMC4N-TP
ESDLC0502P2-TP	ESDLC5V0J4-TP	MBR20P50-TP	MCP20N70-BP	MCU06N40-TP	UMG2N-TP
ESDLC0514MP-TP	ESDLC5V0L4-TP	MBRLP2050-TP	MCPF12N65-BP	MCU60N08-TP	UMG8N-TP
MCU40P04-TP	MCU04N60-TP	MCP55H12-BP			