



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000780

DATE: 20-Jun-14

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	806-0495-20+D	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	DS2401A-00F-00	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	DS2401A-00F-00/T&R	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	DS2401A-030-5A	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	DS2401A-030-5A/T&R	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	DSKCP1P+	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	DSKCP1P+T	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	ICM7218CIJI	ICM7218CIPI+	22-Dec-2014	21-Dec-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	ICM7218CIPI	ICM7218CIPI+	22-Dec-2014	21-Dec-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX11289EWX+	N/A	20-Jun-2014	19-Jun-2016	The part was not released
Discontinuance	MAX11289EWX+T	N/A	20-Jun-2014	19-Jun-2016	The part was not released
Discontinuance	MAX11811ETP+T	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX11835EWA+T	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX11836EWA+	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX11836EWA+T	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX11836EWA+TW	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX11836EWA+W	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX11874EXE+	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX162CMRG	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX24105UTU+	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX3600AGTL/V+	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX3600AGTL/V+T	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX3785UWL+	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX44254AUE+	N/A	20-Jun-2014	19-Jun-2016	The part was not released
Discontinuance	MAX44254EVKIT#	N/A	20-Jun-2014	19-Jun-2016	The part was not released
Discontinuance	MAX5264ACMH	N/A	22-Dec-2014	21-Dec-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX6972ATJ+	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX6973ATJ+	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured
Discontinuance	MAX7300ATI+	N/A	22-Dec-2014	21-Dec-2016	Part can no longer be manufactured

